

| | | |
|---------------------------|------------------------|-----------------|
| LOC I-TPA 110.3 | APP CRS 187° | Rwy Idg 8300 |
| | | TDZE 26 |
| | | Apt Elev 26 |


ILS RWY 19L (CAT II)

TAMPA INTL (TPA)



▽ Simultaneous approach authorized. RADAR required. RVR 1000 authorized with specific OPSPEC, MSPEC, or LOA approval and use of autoland or HUD to touchdown.

⚠ MISSED APPROACH: Climb to 600 then climbing left turn to 2800 on heading 160° and on PIE VORTAC R-138 to GIBBS INT/PIE 29.3 DME and hold.

| | | | | | | | |
|----------------------|--------------------------|-----------------------------|-------------------------------------|-----------------------------------|-------------------------------|--------------------------|-------|
| ARR 126.45 | D-ATIS 128.475 | DEP 118.5 307.175 | TAMPA APP CON 119.5 269.4 | TAMPA TOWER 119.5 269.4 | GND CON 121.7 269.4 | CLNC DEL 133.6 | CPDLC |
|----------------------|--------------------------|-----------------------------|-------------------------------------|-----------------------------------|-------------------------------|--------------------------|-------|



| | | |
|---------|----------|---------|
| ELEV 26 | D | TDZE 26 |
|---------|----------|---------|



| | | | | |
|-----------|-----------|-----|--------|---|
| CATEGORY | A | B | C | D |
| S-ILS 19L | RA 101/12 | 100 | DA 126 | |

CATEGORY II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

SE-3, 15 JUL 2021 to 12 AUG 2021

SE-3, 15 JUL 2021 to 12 AUG 2021