


| | | | |
|--|------------------------|-----------------------------|---|
| WAAS CH 90144 W09A | APP CRS 086° | Rwy Idg TDZE Apt Elev | 5001 4019 4053 |
|--|------------------------|-----------------------------|---|

RNAV (GPS) RWY 9

JEROME COUNTY (JER)

| | |
|--|--|
| RNP APCH. | MISSED APPROACH: (Do not exceed 185K until LAHEW) Climb to 4900 then climbing right turn to 6500 direct LAHEW and hold. # Missed approach requires minimum climb of 300 feet per NM to 5200. |
| <p>For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C. Circling NA north of Rwy 9-27.</p> | |


| | | |
|------------------------|--|---------------------------------|
| ASOS 135.225 | TWIN FALLS APP CON★ 126.7 353.75 | UNICOM 122.8 (CTAF) 0 |
|------------------------|--|---------------------------------|



NW-1, 15 JUL 2021 to 12 AUG 2021

NW-1, 15 JUL 2021 to 12 AUG 2021

| | | | | |
|----------------------|--|------|------|-------|
| 7 NM Holding Pattern | VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 40). | 4900 | 6500 | LAHEW |
|----------------------|--|------|------|-------|



| | |
|-----------|-----------|
| ELEV 4053 | TDZE 4019 |
|-----------|-----------|

| CATEGORY | A | B | C | D |
|--------------|-----------------------|-------------------------|--------------|--------------|
| LPV DA # | | 4544-1½ | 525 (500-1½) | |
| LPV DA | | 4624-1¾ | 605 (600-1¾) | |
| LNAV/VNAV DA | | 4674-1⅞ | 655 (700-1⅞) | |
| LNAV MDA | 4820-1 801 (800-1) | 4820-1¼ 801 (800-1¼) | 4820-2½ | 801 (800-2½) |
| CIRCLING | 4820-1 767 (800-1) | 4820-1¼ 767 (800-1¼) | 4820-2½ | 767 (800-2½) |

