

FREMONT MUNI (FFX)(KFFX) 3 SW UTC-5(-4DT) N43°26.36' W85°59.69'

CHICAGO

772 B NOTAM FILE LAN

H-2L, 10F, L-28I

RWY 01-19: H6501X100 (ASPH-PFC) S-30 MIRL

RWY 01: REIL. VASI(V2L)—GA 3.0° TCH 44'. Tree.

RWY 19: REIL. PAPI(P4L)—GA 3.0° TCH 27'. Trees.

RWY 10-28: H3502X75 (ASPH) S-16 MIRL

RWY 10: Trees.

RWY 28: PAPI(P4L)—GA 3.5° TCH 25'. Trees.

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 01 and Rwy 19; VASI Rwy 01; PAPI Rwy 19 and Rwy 28; MIRL Rwy 10-28 and Rwy 01-19—CTAF.

AIRPORT REMARKS: Attended 1300-2200Z†. For svc after hrs call 231-730-2551. Fuel self-serve. Terminal building access 5-3-2-1. Seaplane activity on adjacent lake 0.5 mile northeast of arpt.

AIRPORT MANAGER: 231-924-7080

WEATHER DATA SOURCES: AWOS-3 118.775 (231) 928-0715.

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ GREAT LAKES APP/DEP CON 119.8 (1030-0500Z†)

Ⓡ CHICAGO CENTER APP/DEP CON 128.5 (0500-1030Z†)

CLNC DEL 118.25

CLEARANCE DELIVERY PHONE: For CD when Great Lakes Apch clsd ctc Chicago ARTCC at 630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE MKG.

MUSKEGON (L) TACAN Chan 99 MKG (115.2) N43°10.16' W86°02.36' 008° 16.3 NM to fld. 659/1W.


TACAN AZIMUTH unusable:

055°-090° byd 10 NM blo 4,000'

281°-360° byd 10 NM blo 8,000'

DME unusable:

281°-360° byd 10 NM blo 8,000'

**FRUITPORT****FLYING-A-RANCH** (39Z) 2 SE UTC-5(-4DT) N43°06.31' W86°07.28'

CHICAGO

630 TPA-1430(800) NOTAM FILE LAN

RWY 09-27: 1925X70 (TURF) LIRL

RWY 09: Thld dspld 327'. Trees.

RWY 27: Trees. Rgt tfc.

SERVICE: S4 LGT Airport lighting not for public use.

AIRPORT REMARKS: Attended irregularly. Arpt is CLOSED Nov-Mar. No snow removal. Fuel avbl for emerg use only. Rwy 09-27 rwy rough and uneven. Rwy 09-27 and dspld thld marked with 3' yellow cones.

AIRPORT MANAGER: 616-846-3977

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3344, when Apch clsd ctc Chicago ARTCC at 630-906-8921.

GAVAGAN FLD (See YALE on page 243)