

**LIVINGSTON CO SPENCER J HARDY** (OZW)(KOZW) 3 NW UTC-5(-4DT) N42°37.77' W83°58.93' **DETROIT COPTER**  
 962 B TPA-2001(1039) NOTAM FILE OZW MON Airport  
**RWY 13-31:** H5002X100 (CONC-GRVD) S-100 HIRL 0.4% up NW **H-10G, L-28J**  
**RWY 13:** MALSR. PAPI(P4L)—GA 3.0° TCH 47'. Trees. **IAP**  
**RWY 31:** REIL. PAPI(P4L)—GA 3.0° TCH 30'. Trees.

**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** HIRL Rwy 13-31 ops low ints dusk-0300Z; to increase ints and **ACTIVATE** after 0300Z†-CTAF. **ACTIVATE** REIL Rwy 31 and MALSR Rwy 13—CTAF. PAPI Rwy 13 and Rwy 31 ops dawn-dusk, thereafter—CTAF.

**AIRPORT REMARKS:** Attended Mon-Fri 1200-2200Z†, Sat-Sun 1300-1700Z†. Deer and birds on and in/ov arpt.

**AIRPORT MANAGER:** 517-546-6675

**WEATHER DATA SOURCES:** AWOS-3 118.875 (517) 546-4450.

**COMMUNICATIONS:** CTAF/UNICOM 123.0

Ⓡ **DETROIT APP/DEP CON** 132.35

**CLNC DEL** 121.725

**GCO** 121.725 (DETROIT METRO CLNC and FLIGHT SERVICES)

**CLEARANCE DELIVERY PHONE:** For CD ctc Detroit Apch at 800-499-8181.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAN.

**SALEM (L) VORTACW** 114.3 SVM Chan 90 N42°24.52' W83°35.63' 311° 21.7 NM to fld. 956/3W.


**TACAN AZIMUTH** unusable:

215°-255° byd 10NM

Within 10 NM blo 6,000'

**ILS/DME** 108.55 I-OGO Chan 22(Y) Rwy 13. ILS/DME unmonitored. DME unusable byd 25° right of course.

**COMM/NAV/WEATHER REMARKS:** For Clnc Del key frequency 121.725 4 times. To contact FSS key frequency 121.725 6 times; one second on/one second off; monitor 121.725 while electronic equipment dials DET Clnc Del/Lansing FSS.



**RAETHER** (4Y1) 6 SE UTC-5(-4DT) N42°33.92' W83°51.38' **DETROIT COPTER**  
 984 NOTAM FILE LAN

**RWY 17-35:** 2206X70 (TURF)

**RWY 17:** Thld dsplcd 757'. Trees.

**RWY 35:** Thld dsplcd 740'. Road.

**AIRPORT REMARKS:** Unattended. Deer and birds on and in/ov rwy. Ultralight activity on and in/ov arpt. Heavy equipment adjacent to west side of Rwy 35. Rwy 17-35 thld and dsplcd thlds marked with 3' cones.

**AIRPORT MANAGER:** 517-546-4498

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Detroit Apch at 800-499-8181.

**HURON CO MEML** (See BAD AXE on page 150)

## INDIAN RIVER

**CAMPBELL-PRATT** (Y65) 1 E UTC-5(-4DT) N45°24.50' W84°36.00' **LAKE HURON L-31C**  
 602 NOTAM FILE LAN

**RWY 10-28:** H3006X50 (ASPH) LIRL

**RWY 10:** Trees.

**RWY 28:** Thld dsplcd 600'. Trees.

**SERVICE:** LGT **ACTIVATE** LIRL Rwy 10-28—CTAF.

**AIRPORT REMARKS:** Attended irregularly. Snow removal intermittent, call 517-202-9926 to verify condition. Deer and birds on and in/ov arpt.

**AIRPORT MANAGER:** (517) 202-9926

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE PLN.

**PELLSTON (L) VORTACW** 111.8 PLN Chan 55 N45°37.84' W84°39.85' 175° 13.6 NM to fld. 835/6W.

**VOR** unusable:

301°-339°

GCP has azm only, no DME at GCP