

MARLETTE TOWNSHIP (77G) 1 SW UTC-5(-4DT) N43°18.71' W83°05.46'

DETROIT

895 B NOTAM FILE LAN

L-28J

RWY 09-27: H3795X75 (ASPH) MIRL

RWY 09: PAPI(P2R)—GA 3.0° TCH 44'. Trees.

RWY 27: PAPI(P2L)—GA 3.0° TCH 45'. Trees.

RWY 01-19: H3500X75 (ASPH) MIRL 0.7% up N

RWY 01: PAPI(P2L)—GA 3.0° TCH 21'.

RWY 19: PAPI(P2L)—GA 3.0° TCH 40'. Trees.

SERVICE: FUEL 100LL, MOGAS LGT Actvt PAPI Rwy 01, 09, 19 and 27; MIRL Rwy 01-19 & Rwy 09-27—CTAF.

AIRPORT REMARKS: Unattended. Deer & lrg birds on & invof arpt. Fuel avbl H24 self ser via credit card.

AIRPORT MANAGER: 810-459-4674


COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **CLEVELAND CENTER APP/DEP CON** 122.7

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0224/0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE LAN.

PECK (H) TACAN Chan 87 ECK (114.0) N43°15.35' W82°43.08' 289° 16.7 NM to fld. 810/7W.



MARQUETTE

SAWYER INTL (SAW)(KSAW) 17 S UTC-5(-4DT) N46°20.95' W87°23.78'

GREEN BAY

1205 B ARFF Index—See Remarks NOTAM FILE SAW MON Airport

H-2K, L-31A

RWY 01-19: H9072X150 (ASPH-GRVD) S-114, D-181, 2S-175,

2D-317, 2D/2D2-741 PCN 43 F/B/X/U HIRL

RWY 01: MALSR. PAPI(P4L)—GA 3.0° TCH 51'.

RWY 19: REIL. PAPI(P4L)—GA 3.0° TCH 53'. 0.5% down.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 01: TORA-9072 TODA-9072 ASDA-9072 LDA-9072

RWY 19: TORA-9072 TODA-9072 ASDA-9072 LDA-9072

SERVICE: S4 FUEL 100LL, JET A OX 1, 2 LGT When twr clsd ACTIVATE MALSR Rwy 01; REIL Rwy 19; PAPI Rws 01 and Rwy 19; HIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Attended 1000-0100Z†. For svc after hrs call 906-222-3062 (pager). FBO svc after hrs contact 906-222-3062. Birds and deer on and invof arpt. PAEW on arpt monitor 119.975 (CTAF). Class I, ARFF Index B. Air carrier ops are not authorized in excess of 15 minutes before or after scheduled arrival/dep times without prior coordination with arpt manager. Unscheduled air carrier operations with more than 30 passenger seats require 48 hour prior permission, call arpt manager 906-346-3308 or 906-364-0939. Index C ARFF avbl with 48 hr hour prior permission, call arpt manager 906-346-3308 or 906-364-0939. General aviation and charter actf parking avbl at general aviation terminal only, lctd SE corner of arpt. S half of air carrier terminal ramp not plowed Oct-Apr. Frequent snow removal ops in progress various times Oct-Apr. Monitor CTAF. North air carrier ramp entrance/exit clsd 15 Nov-15 Apr. Ramp fees in effect. Ramp fees may be waived with fuel purchase. FBO svc after hrs ctc 906-222-3062 (pager).

AIRPORT MANAGER: 906-346-3308

WEATHER DATA SOURCES: AWOS-3 118.375 (906) 346-5126.

COMMUNICATIONS: CTAF 119.975 UNICOM 122.7

RCO 122.5 (GREEN BAY RADIO)

Ⓡ **MINNEAPOLIS CENTER APP/DEP CON** 119.1

TOWER 119.975 (1100-0300Z†) **GND CON** 121.65

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Minneapolis ARTCC at 651-463-5588.

AIRSPACE: CLASS D svc 1100-0300Z†; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAW.

(H) VOR/DME 117.1 SAW Chan 118 N46°21.54' W87°23.85' at fld. 1196/4W.

VOR unusable:

330°-090° byd 10 NM blo 8,000'

DME unusable:

250°-090° byd 30 NM blo 4,500'

ILS 110.1 I-SOU Rwy 01. Class IE. Autopilot coupled apch na blw 1,360' MSL.

COMM/NAV/WEATHER REMARKS: No emergency frequencies at twr.

