

NAILR N38°27.26' W77°54.32' NOTAM FILE CJR.
NDB (MHW) 351 MSQ 037° 4.8 NM to Culpeper Rgnl. 289/10W.
 NDB unusable:
 260°-355° byd 15 NM

WASHINGTON
 L-29E, 34E, 36I, A

NEW KENT CO (See QUINTON on page 369)

NEW LONDON (See FOREST on page 346)

NEW MARKET (8W2) 2 W UTC-5(-4DT) N38°39.36' W78°42.51'
 963 B TPA-1788(825) NOTAM FILE DCA
RWY 06-24: H2920X60 (ASPH) LIRL(NSTD)

WASHINGTON
 L-22G
 IAP

RWY 06: Trees. Rgt tfc.

RWY 24: Thld displcd 918'. Pole.

SERVICE: S4 FUEL 100LL LGT Rwy 06-24 NSTD LIRL, thld lgts one fixture each side. Rwy 06 lgtd thld relocated 100' and Rwy 24 lgtd thld relocated 930' for ngt ops, 2020' Rwy 06-24 lgts at ngt. No rwy end lgts Rwy 24. Arpt lights and rotating bcn opr SS-SR.

AIRPORT REMARKS: Attended Mon-Fri 1300-2130Zt. Unattended

Thanksgiving, Christmas and New Years day. Parachute Jumping. Deer and birds on and in/ov rwy. Skydiving ops within 2 NM of the arpt from 0800-SS every weekend and occasionally during the week. Hot air balloons weekends early morning and late afternoon. Arriving pilots should use caution. Fuel 24 hr credit card svc. Balloon repair station. Acft repairs avbl, but not full-time. Power plant repairs avbl, but not full-time. Approximately 1000' north of rwy, 200' ridge/trees parallel rwy.

AIRPORT MANAGER: 703-327-0444

WEATHER DATA SOURCES: AWOS-3 118.175 (540) 740-3801.

COMMUNICATIONS: CTAF/UNICOM 122.8

® WASHINGTON CENTER APP/DEP CON 133.2

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.

LINDEN (L) VORTACW 114.3 LDN Chan 90 N38°51.26' W78°12.33' 249° 26.4 NM to fld. 2435/6W.

DME portion unusable:

115°-150° byd 20 NM blo 3,500'

150°-155° byd 20 NM blo 4,000'


155°-175° byd 20 NM blo 4,500'

175°-200° byd 20 NM blo 5,000'

200°-225° byd 20 NM blo 5,500'

TACAN AZIMUTH unusable:

115°-225° byd 20 NM



NEW RIVER VALLEY (See DUBLIN on page 344)