

LOPEZ**FISHERMANS BAY SPB** (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08'

SEATTLE

00 NOTAM FILE SEA

WATERWAY 05W-23W: 3000X150 (WATER)**WATERWAY 05W:** Rgt tfc.**SEAPLANE REMARKS:** Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay.**AIRPORT MANAGER:** 360-468-4116**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Whidbey Apch at 360-257-3310.**LOPEZ ISLAND** (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26'

SEATTLE

209 B NOTAM FILE SEA

RWY 16-34: H2905X61 (ASPH-GRVD) S-12.5 MIRL 1.6% up N**RWY 16:** REIL. PAPI(P2L)—GA 4.0° TCH 43'. Trees. Rgt tfc.**RWY 34:** REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees.**AIRPORT REMARKS:** Unattended. Rwy 16-34 soft shoulders and thlds.**AIRPORT MANAGER:** 360-468-4116**COMMUNICATIONS:** CTAF 128.25**CLEARANCE DELIVERY PHONE:** For CD ctc Whidbey Apch at 360-257-3310.**LOST RIVER** (See MAZAMA on page 198)**LOWER GRANITE STATE** (See COLFAX on page 182)**LOWER MONUMENTAL STATE** (See KAHLOTUS on page 193)**LYNDEN MUNI/JANSEN FLD** (38W) 1 N UTC-8(-7DT) N48°57.35' W122°27.49'

SEATTLE

106 B NOTAM FILE SEA

RWY 07-25: H2425X40 (ASPH) S-12 MIRL(NSTD)**RWY 07:** PAPI(P2L)—GA 3.0° TCH 15'. Thld dspcd 262'. Trees.**RWY 25:** PAPI(P2R)—GA 6.0° TCH 15'. Thld dspcd 433'. Trees.**SERVICE:** FUEL 100LL LGT Rwy 07-25 NSTD MIRL. Use 3 clicks to ACTIVATE MIRL Rwy 07-25 and rotating bcn—CTAF.**AIRPORT REMARKS:** Unattended. Automated credit card system for fuel. Exposed ditch Rwy 07-25. Avoid ngt ldgs to Rwy 25.

Ngt ldgs should be performed on Rwy 07, winds permitting. 1850' between thld lgts, Rwy 07 thld lgts located 134' prior to dspcd thld. Rwy 07 thld relocated 155' for ngt ops. Rwy 25 thld relocated 434' for ngt ops, 1871' usable for ngt ops. No white/red lgts past dspcd thld. Run-ups not permitted on Rwy 25 turn around twy. Fly PAPI on all approaches to Rwy 07. Rwy 25 departures use full length of available Rwy TODA 2425 ft. WSDOT kiosk lctd at fuel stn. Bicycles avbl in pilot's lounge.

AIRPORT MANAGER: 360-354-3446**COMMUNICATIONS:** CTAF 122.9**VICTORIA TERMINAL APP/DEP CON** 132.7 290.8 604-586-4560**COMM/NAV/WEATHER REMARKS:** Automated UNICOM; 3 clicks.**MANSFIELD** (8W3) 0 E UTC-8(-7DT) N47°48.56' W119°38.22'

SEATTLE

2272 B NOTAM FILE SEA

RWY 03-21: H2575X46 (ASPH) LIRL**RWY 03:** Road.**RWY 21:** Road.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 03:** TORA-2400**RWY 21:** TORA-2400**SERVICE:** LGT Rwy 03-21 no rwy lgts northside of Rwy 21 end to midfield.**AIRPORT REMARKS:** Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 has widespread, open unsealed cracks and joints. Rwy 03-21 markings faded. Pilots bring own ropes.**AIRPORT MANAGER:** 509-884-2494**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**MARTIN FLD** (See COLLEGE PLACE on page 183)