

CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: 253-982-5611

WEATHER DATA SOURCES: ASOS (253) 982-3434

COMMUNICATIONS: D-ATIS 135.825 270.1 PTD 372.2

⑧ SEATTLE APP/DEP CON 126.5 377.15

TOWER 124.8 259.3 GND CON 118.175 279.65

COMD POST 349.4 134.1

PMSV METRO 342.3 Full wx svc avbl H24 exc dur afld/twr closure. DSN 382-3434/2112, C253-982-3434/2112. All obs provided by AN/FMQ-19 automated observing sys; augmented by human obsn when nec. Full svc PMSV avbl via phone patch with comd post. Tran aircrew ctc 25 OWS dur afld closure to request wx briefing DSN 228-6598, or C520-228-6598. when possible provide 3 hr pn for all rqr briefings.

AIRSPACE: CLASS D.

RADIO AIDS TO NAVIGATION: NOTAM FILE TCM.

(T) TACAN Chan 33 TCM (109.6) N47°08.86' W122°28.50' at fld. 283/15E.

No NOTAM MP 0800-1700Z‡ and 2100-2300Z‡ Wed

ILS 109.9 I-MAR Rwy 16. Class 1A. Ry 16-34 backcourse unusable. Ry 16-34 No NOTAM MP 0800-1700Z‡ and 2100-2300Z‡ Tue and Thu.

ILS 108.5 I-TCM Rwy 34. Class IIE. Ry 16-34 backcourse unusable. Ry 16-34 No NOTAM MP 0800-1700Z‡ and 2100-2300Z‡ Tue and Thu.

MEAD FLYING SERVICE (70S) 1 N UTC-8(-7DT) N47°47.23' W117°21.49'

SEATTLE

1905 TPA-2505(600) NOTAM FILE SEA

RWY 16-34: H2481X30 (ASPH)

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Attended continuously. No winter maintenance.

AIRPORT MANAGER: 253-880-7805

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2522

MEARS FLD (See CONCRETE on page 183)**METALINE FALLS****SULLIVAN LAKE STATE** (09S) 3 SE UTC-8(-7DT) N48°50.45' W117°17.04'

SEATTLE

2614 NOTAM FILE SEA

RWY 16-34: 1765X100 (TURF)

RWY 16: Trees.

RWY 34: Sign.

AIRPORT REMARKS: Unattended. Arpt clsd 1 Oct-1 June exc for apvd mil and public safety/law enforcement helicopter ops.

Vehicles, pedestrians, and animals on and invof arpt. Watch for gnd squirrel holes in rwy. Rwy 16-34 scf rough. Trees both sides in transition sfc. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Gnd drops rapidly byd Rwy 16-34 ends. Rwy marked with reflectors dur dates arpt is open. 2 wind socks, one on each rwy end.

AIRPORT MANAGER: (360) 618-2477

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

METHOW VALLEY STATE (See WINTHROP on page 232)**MONROE****FIRST AIR FLD** (W16) 2 NW UTC-8(-7DT) N47°52.28' W121°59.71'

SEATTLE

50 NOTAM FILE SEA

RWY 07-25: H2087X34 (ASPH) RWY LGTS(NSTD)

RWY 07: Rgt tfc.

RWY 25: Thld dspld 500'.

SERVICE: S4 LGT SS-SR. Solar powered lighting.

AIRPORT REMARKS: Attended Oct-Mar 1700Z‡-dark, Apr-Sept 1700-0300Z‡. Parachute Jumping. Tran tie downs have no ropes, pilots must supply own. Additional tran parking avbl SE corner of rwy. Rwy 25 acft parked in primary sfc. Rwy 07 numbers 200' E of dspld thr; numbers only; no cntrn. Word "MONROE" painted midfield on rwy.

AIRPORT MANAGER: 360-794-8570

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.