

SEQUIM VALLEY (W28) 4 NW UTC-8(-7DT) N48°05.88' W123°11.28'

SEATTLE

151 B NOTAM FILE SEA

L-1E

RWY 09-27: H3508X40 (ASPH) LIRL

RWY 09: Trees. Rgt tfc.

RWY 27: Trees.

SERVICE: FUEL 100LL LGT Beacon OTS indefinitely.

AIRPORT REMARKS: Unattended. Self svc fuel avbl 24 hrs. Wildlife on and in/ovf arpt. Rwy 09-27 has a 6" shoulder. Ldg fee.

AIRPORT MANAGER: 360-670-3083


COMMUNICATIONS: CTAF/UNICOM 122.7

CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

RADIO AIDS TO NAVIGATION: NOTAM FILE SEA.

TATOOSH (H) VORTACW 112.2 TOU Chan 59 N48°17.99'

W124°37.62' 079° 59.0 NM to fld. 1650/22E.



SHADY ACRES (See SPANAWAY on page 221)

SHELTON

SANDERSON FLD (SHN)(KSHN) 3 NW UTC-8(-7DT) N47°14.01' W123°08.85'

SEATTLE

273 B NOTAM FILE SHN

H-1B, L-1D

RWY 05-23: H5005X100 (ASPH) S-55, D-72, 2D-130

IAP

PCN 17 F/A/Y/T MIRL 0.3% up NE

RWY 05: Trees. Rgt tfc.

RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 47'. Trees.

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT REIL Rwy 23; PAPI Rwy 23; MIRL Rwy 05-23—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-0030Z \ddagger . Parachute Jumping. Parachute operations on the field avoid crossing midfield to enter traffic pattern. 24 hr credit card fuel facility. Bcn on water twr north of rwy.

AIRPORT MANAGER: 360-426-1151

WEATHER DATA SOURCES: ASOS 119.275 (360) 426-6332.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ SEATTLE APP/DEP CON 121.1

CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4723.

RADIO AIDS TO NAVIGATION: NOTAM FILE OLM.

OLYMPIA (H) VORTACW 113.4 OLM Chan 81 N46°58.30'

W122°54.11' 308° 18.7 NM to fld. 200/19E.


TACAN AZIMUTH & DME unusable:

223°-258° byd 20 NM blo 4,100'

258°-283° byd 30 NM blo 4,100'

358°-043° byd 10 NM blo 6,000'

358°-043° byd 20 NM blo 7,000'



SILVERDALE

APEX AIRPARK (8W5) 2 NW UTC-8(-7DT) N47°39.38' W122°43.99'

SEATTLE

525 B NOTAM FILE SEA

RWY 17-35: H2500X28 (ASPH) LIRL 0.8% up N

RWY 17: Trees.

RWY 35: Trees. Rgt tfc.

SERVICE: S4

AIRPORT REMARKS: Attended 1800-0300Z \ddagger . Children and pets etc in/ovf arpt. No line of sight between rwy ends. Twy east side rwy. Be alert on twy. Trees, acct and bldgs in transition sfc. Avoid overflt of warehouse lctd at Rwy 34 end.

AIRPORT MANAGER: 206-390-4131

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.

SKAGIT RGNL (See BURLINGTON/MOUNT VERNON on page 179)