

MELBOURNE ORLANDO INTL (MLB)(KMLB) 2 NW UTC-5(-4DT) N28°06.17' W80°38.72'

JACKSONVILLE
H-81, L-24F
IAP, AD

33 B Class I, ARFF Index C NOTAM FILE MLB

RWY 09R-27L: H10181X150 (ASPH-GRVD) S-100, D-165, 2D-300
PCN 74 F/A/X/T HIRL CL

RWY 09R: MALSR, TDZL, PAPI(P4L)—GA 3.0° TCH 83'. RVR-T
RWY 27L: REIL, PAPI(P4L)—GA 3.0° TCH 54'. RVR-R Thld dsplcd
699'. Trees.

RWY 09L-27R: H6000X150 (ASPH-GRVD) S-60, D-60
PCN 31 F/B/X/T MIRL

RWY 09L: PAPI(P4L)—GA 3.0° TCH 39'. Trees.
RWY 27R: PAPI(P4L)—GA 3.0° TCH 40'. Bldg.

RWY 05-23: H3001X75 (ASPH) S-26 PCN 9 F/A/Y/T MIRL

RWY 05: PAPI(P2L)—GA 3.0° TCH 21'. Trees.
RWY 23: PAPI(P2L)—GA 3.0° TCH 21'. Hangar.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 05: TORA-3000 TODA-3000 ASDA-3000 LDA-3000
RWY 09L: TORA-6000 TODA-6000 ASDA-6000 LDA-6000
RWY 09R: TORA-10181 TODA-10181 ASDA-10181 LDA-10181
RWY 23: TORA-3000 TODA-3000 ASDA-3000 LDA-3000
RWY 27L: TORA-10181 TODA-10181 ASDA-10181 LDA-9482
RWY 27R: TORA-6000 TODA-6000 ASDA-6000 LDA-6000

SERVICE: S4 **FUEL** 100LL, JET A **LGT** When ATCT clsd, ACTVT
MALSR Rwy 09R; REIL Rwy 27L; PAPI Rwy 09R and 27L; MIRL
05-23 and 09L-27R; HIRL Rwy 09R-27L—CTAF.

AIRPORT REMARKS: Attended continuously. Bird act on and invof arpt. Sfc cond not rprtd 0400-1100Z†. TGL na aft 0200Z† or 2 hr aft SS; whichever is later. Uncontrolled area Twy V west of Rwy 05; Twy C north of Twy K; Twy S north of S1; Twy H and G. Rwy 09R RVR unavailable 0500-1100Z†. Rwy 27L RVR unavailable 0500-1100Z†. Rwy 09R-27L 400' blast pad both rwy ends. U.S. CSTMS user fee arpt. Rwy 05-23 not avbl for sked acr opns with more than 9 pax seats or unsked acr at least 31 pax seats.

AIRPORT MANAGER: 321-723-6227

WEATHER DATA SOURCES: ASOS 132.55 (321) 951-7575. LAWRS.

COMMUNICATIONS: CTAF 118.2 ATIS 132.55 **UNICOM** 122.95

RCO 122.1R 110.0T (SAINT PETERSBURG RADIO)

® **ORLANDO APP/DEP CON** 132.65

TOWER 118.2 124.05 (1100-0500Z†)

GND CON 121.9 **CLNC DEL** 121.9 132.65 (when twr clsd)

AIRSPACE: CLASS D svc 1100-0500Z†; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE MLB.

(H) **VOR/DME** 115.85 MLB Chan 105(Y) N28°06.32' W80°38.12' at fld. 30/7W.

ILS 108.3 I-MLB Rwy 09R. Unmonitored when ATCT clsd.

