

CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

(H) VOR/DME 117.9 DEN Chan 126 N39°48.75' W104°39.64' 341° 3.0 NM to fld. 5452/8E.

VOR unusable:

- 180°-200° byd 20 NM blo 14,000'
- ILS/DME 111.55 I-DZG Chan 52(Y) Rwy 07. Class IE.
- ILS/DME 108.9 I-FUI Chan 26 Rwy 08. Class IE.
- ILS/DME 111.1 I-LTT Chan 48 Rwy 16L. Class IE.
- ILS/DME 111.9 I-DQQ Chan 56 Rwy 16R. Class IT.
- ILS/DME 110.15 I-BXP Chan 38(Y) Rwy 17L. Class IE.
- ILS/DME 108.5 I-ACX Chan 22 Rwy 17R. Class IE.
- ILS/DME 111.55 I-ERP Chan 52(Y) Rwy 25. Class IE.
- ILS/DME 108.9 I-JOY Chan 26 Rwy 26. Class 1E.
- ILS/DME 111.9 I-DXU Chan 56 Rwy 34L. Class IIIE.
- ILS/DME 111.1 I-OUF Chan 48 Rwy 34R. Class IIIE.
- ILS/DME 108.5 I-AQD Chan 22 Rwy 35L. Class IIIE.
- ILS/DME 110.15 I-DPP Chan 38(Y) Rwy 35R. Class IIIE.

COMM/NAV/WEATHER REMARKS: Emerg frequency 121.5 not avbl at twr.

ROCKY MOUNTAIN METRO (BJC)(KBJC) 9 NW UTC-7(-6DT) N39°54.53' W105°07.03'

DENVER

5673 B ARFF Index—See Remarks NOTAM FILE BJC

H-3F, 5A, L-10F, A

RWY 12L-30R: H9000X100 (ASPH-GRVD) S-65, D-105, 2S-95, 2D-150 PCN 31 F/D/W/T HIRL

IAP, AD

RWY 12L: REIL. PAPI(P4L)—GA 3.0° TCH 41'. 1.0% down.

RWY 30R: MALSR. PAPI(P4L)—GA 3.0° TCH 52'. Rgt tfc. 1.1% up.

RWY 12R-30L: H7002X75 (ASPH-GRVD) S-47, D-61

PCN 18 F/D/X/T MIRL 1.1% up NW

RWY 12R: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Rgt tfc.

RWY 30L: REIL. PAPI(P2L)—GA 3.0° TCH 41'.

RWY 03-21: H3600X75 (ASPH) S-40, D-45, 2D-65 MIRL 0.4% up S

RWY 03: PAPI(P2L)—GA 3.0° TCH 30'.

RWY 21: PAPI(P2L)—GA 3.0° TCH 40'. Rgt tfc.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 03: TORA-3600 TODA-3600 ASDA-3600 LDA-3600

RWY 12L: TORA-9000 TODA-9000 ASDA-9000 LDA-9000

RWY 12R: TORA-7002 TODA-7002 ASDA-7002 LDA-7002

RWY 21: TORA-3600 TODA-3600 ASDA-3600 LDA-3600

RWY 30L: TORA-7002 TODA-7002 ASDA-7002 LDA-7002

RWY 30R: TORA-9000 TODA-9000 ASDA-9000 LDA-9000

SERVICE: S4 FUEL 100LL, JET A OX 1, 2, 3, 4 LGT When twr closed

ACTIVATE MIRL Rwy 03-21, and Rwy 12R-30L, HIRL Rwy 12L-30R, MALSR Rwy 30R, PAPI Rwy 03, Rwy 21, Rwy 12L, Rwy 12R, Rwy 30L, and Rwy 30R and REIL Rwy 12L, Rwy 12R and Rwy 30L—CTAF.

NOISE: Voluntary noise abatement procedure in effect ctc noise office 303-271-4850.

AIRPORT REMARKS: Attended continuously. 100LL self svc. Birds and other wildlife on and in/ovf rwy. Watch for wildlife on or near rwy. Helicopters arr/dep from rwy and twys. Pilots are requested to avoid ft due to nesting eagles: Below 6500' MSL, BJC VOR 25°, 2.7 DME; Over Standley Lake below 8000' MSL, BJC VOR 150°, 3.0 DME. Class II ARFF Index A, 24 hr PPR for unscheduled air carrier ops with more than 30 passengers seats call 720-352-0395. ARFF Index B also avbl PPR ctc arpt 720-352-0395. U.S. Customs user fee arpt. Twy C1 and Twy D only marked with reflectors. North terminal ramp slope exceeds FAA recommended stds. Flight Notification Service (ADCUS) avbl. NOTE: See Special Notices—Extensive Helicopter Flight Training. USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

AIRPORT MANAGER: (303) 271-4851

WEATHER DATA SOURCES: AWOS-3 (720) 887-8067

COMMUNICATIONS: CTAF 118.6 ATIS 126.25 303-466-8744

DENVER APP/DEP CON 125.12

METRO TOWER 118.6 (1300-0500Z)± GND CON 121.7 CLNC DEL 132.6

AIRSPACE: CLASS D svc 1300-0500Z±; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE BJC.

JEFFCO (H) VOR/DME 115.4 BJC Chan 101 N39°54.78' W105°08.34' 093° 1.0 NM to fld. 5737/11E.

VOR portion unusable:

226°-245° byd 36 NM blo 17,000'

246°-278° byd 30 NM blo 19,000'

279°-300° byd 34 NM blo 18,000'

DME unusable:

246°-278° byd 30 NM

ILS 111.7 I-BJC Rwy 30R. Class IA. Unmonitored when ATCT closed.

COMM/NAV/WEATHER REMARKS: Emerg frequency 121.5 not avbl at twr.

