


# HI-TACAN RWY 21L

TACAN LUF Chan <b>77</b>	APCH CRS <b>213°</b>	Rwy ldg <b>9904</b> TDZE <b>1084</b> Arprt Elev <b>1085</b>	JAL-321 [USAF]	LUKE AFB (KLUF)
-----------------------------	-------------------------	---	----------------	-----------------

**ALSF-1**  
 MISSED APPROACH: Climbing to 5000, intercept LUF TACAN R-210 to 19 DME (CESAT). Contact LUKE APP CON.  
 \* When ALS inop, increase vis to 1 3/8 miles.

ATIS ★ <b>134.925 269.9</b>	LUKE APP CON <b>118.15 363.125</b>	LUKE TOWER ★ <b>119.1 379.9</b>	GND CON <b>133.175 335.8</b>	CLNC DEL <b>126.25 273.475</b>
--------------------------------	---------------------------------------	------------------------------------	---------------------------------	-----------------------------------



EMERG SAFE ALT 100 NM 17,200			ELEV 1085	TDZE 1084
5000 LUF R-210	CESAT LUF 19	LENNI 22		
CATEGORY	C	D	E	
S-21L *	1580/50	496	(500-1)	
CIRCLING	NOT AUTHORIZED			
HIRL all Rwy				

# HI-TACAN RWY 21L

SW-4, 09 SEP 2021 to 07 OCT 2021

SW-4, 09 SEP 2021 to 07 OCT 2021