

ARRIVAL ROUTE DESCRIPTION

- BERTH TRANSITION (BERTH.RIDES1)
- CHEFS TRANSITION (CHEFS.RIDES1)
- KUTNE TRANSITION (KUTNE.RIDES1)
- LAIZY TRANSITION (LAIZY.RIDES1)
- OCTAL TRANSITION (OCTAL.RIDES1)
- SPIFF TRANSITION (SPIFF.RIDES1)
- WAPOM TRANSITION (WAPOM.RIDES1)

KMCO: From RIDES on track 344° to WISRD.

LANDING KMCO RUNWAYS 17L/R, 18L/R: From WISRD on track 360° to cross THEAM at or above 10000, then on track 001° to cross PARRX between 9000 and 11000 and at 250K, then on track 005° to cross HAANZ between 8000 and 9000 and at 220K, then on track 006° to cross PTMAN at 5000 and at 210K, then on track 006°. Expect RADAR vectors to final approach course.

LANDING KMCO RUNWAYS 35L/R, 36L/R: From WISRD on track 339° to cross HAHNA at 6000 and at 210K, then on track 339°. Expect ILS or RNAV 35R approach or RADAR vectors to final approach course.

LANDING KISM: From RIDES on track 343° to cross WIDGET at 8000, then on heading 290° or as assigned by ATC. Expect RADAR vectors to final approach course.

LANDING KLEE/KSFB/KORL: From RIDES on track 346° to cross MPLEX at 12000 and at 280K, then on heading 351° or as assigned by ATC. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS:

KMCO LANDING NORTH: Continue track to HAHNA, conduct Rwy 35R approach.

KMCO LANDING SOUTH: Continue track to PTMAN, then proceed direct HAMMY, conduct Rwy 18R approach.

SE-3, 09 SEP 2021 to 07 OCT 2021

SE-3, 09 SEP 2021 to 07 OCT 2021