

DOWAGIAC MUNI (C91) 1 NW UTC-5(-4DT) N41°59.58' W86°07.70'

747 B TPA—1547(800) NOTAM FILE LAN

RWY 09-27: H4700X100 (ASPH) S-30, D-60 MIRL

RWY 09: REIL. PAPI(P4L)—GA 3.0° TCH 35'. Trees.

RWY 27: REIL. PAPI(P4L)—GA 3.0° TCH 35'. Trees. Rgt tfc.

RWY 04-22: 2176X100 (TURF)

RWY 04: Trees.

RWY 22: Thld dspclcd 388'. Tree. Rgt tfc.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 09-27; PAPI Rwy 09 and Rwy 27; REIL Rws 09 and 27—CTAF.

AIRPORT REMARKS: Unattended. Self svc fuel avbl 24 hrs. Deer and birds on and invof arpt. Model RC acct ops E side of Rwy 04-22. Admin bldg access, depress V, then III-II simultaneous, then I. Rwy 04-22 and dspcl thld marked with 3' yellow cones.

AIRPORT MANAGER: (269) 591-0054

COMMUNICATIONS: CTAF/UNICOM 122.8

KELLER RCO 122.1R 116.6T (LANSING RADIO)

Ⓡ **SOUTH BEND APP/DEP CON** 118.55 (1030-0500Z† Sun-Fri, 1030-0445Z† Sat), other times ctc

Ⓡ **CHICAGO CENTER APP/DEP CON** 127.55

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.


RADIO AIDS TO NAVIGATION: NOTAM FILE LAN.

KEELER (L) VOR/DME 116.6 ELX Chan 113 N42°08.66' W86°07.36' 182° 9.1 NM to fld. 794/0E.

CHICAGO

L-281

IAP



DRUMMOND ISLAND

DRUMMOND ISLAND (DRM)(KDRM) 1 SW UTC-5(-4DT) N46°00.56' W83°44.64'

668 B TPA—1668(1000) LRA NOTAM FILE DRM

RWY 08-26: H4000X75 (ASPH) MIRL

RWY 08: PAPI(P2L)—GA 3.0° TCH 35'. Thld dspclcd 650'. Trees.

RWY 26: PAPI(P2L)—GA 3.0° TCH 25'. Thld dspclcd 170'. Road.

RWY 01-19: 2500X150 (TURF)

RWY 01: Trees.

RWY 19: Trees.

SERVICE: S4 FUEL 100LL, MOGAS OX1, 3 LGT ACTIVATE MIRL Rwy 08-26 and PAPI Rwy 08 and 26—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1300-2200Z†. Birds and deer invof arpt. Occasional golf carts and pedestrians crossing Rwy 08-26 due to golf course on both sides. Drummond Island, Yacht Haven SPB located 1.5 mile north, customs avbl 906-632-8822, 906-632-7221. Rwy 01-19 marked with 3' yellow cones. Rwy 01-19 center 20' portion of rwy from intersection Rwy 08-26 north to the hangar line is asph; remainder of rwy turf. Flight Notification Service (ADCUS) available.

AIRPORT MANAGER: 906-493-5411

WEATHER DATA SOURCES: AWOS-3 118.325 (906) 493-6410.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **TORONTO CENTER APP/DEP CON** 132.65

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE CIU.

SAULT STE MARIE (H) VOR/DME 112.2 SSM Chan 59 N46°24.73' W84°18.89' 139° 33.9 NM to fld. 687/4W.

VOR unusable:

085°-105° byd 10 NM blo 5,000'

085°-105° byd 20 NM blo 8,000'

LAKE HURON

L-31C

IAP

