

MARINA MUNI (OAR)(KOAR) 2 NE UTC-8(-7DT) N36°40.89' W121°45.70' **SAN FRANCISCO**
 137 B NOTAM FILE OAK **L-3B**
RWY 11-29: H3483X75 (ASPH) S-20, D-50 MIRL **IAP**
RWY 29: PAPI(P2L)—GA 3.0° TCH 45'. Rgt tfc.
SERVICE: S4 **FUEL** 100LL, JET A **OX** 3, 4 **LGT** ACTIVATE MIRL Rwy 11-29—CTAF 7 clicks.
NOISE: Depart Rwy 29 execute 45° rgt turn to avoid overflight of noise sensitive residential area.
AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z†. Fuel avbl (100LL and Jet A) 24 hrs via credit card lock system.
 Parachute Jumping. Ultralight and skydiving activity on and invof arpt. Skydiving activity on SE side of arpt. Rwy 29 calm wind rwy. 500' stopway departure end Rwy 29.
AIRPORT MANAGER: (831) 241-8628
WEATHER DATA SOURCES: AWOS-3PT 134.025 (831) 384-2967.
COMMUNICATIONS: CTAF/UNICOM 122.7
 Ⓡ **NORCAL APP/DEP CON** 133.0 (340°-144°)
CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-3748.
RADIO AIDS TO NAVIGATION: NOTAM FILE SNS.
SALINAS (H) VORTACW 117.3 SNS Chan 120 N36°39.83' W121°36.19' 261° 7.7 NM to fld. 80/17E.
 VOR portion unusable:
 010°-016° byd 22 NM blo 7,000'
 010°-016° byd 26 NM blo 8,000'
 016°-080° byd 22 NM blo 8,000'
 150°-170° byd 8 NM blo 10,000'
 TACAN AZIMUTH & DME unusable:
 010°-080° byd 22 NM blo 8,000'
 150°-200° blo 11,000'
 aerobatic acft wi an area defined as .5 NM rds of SNS 357016.4 (5.3 NM W CVH), blo 3000', avoidance advised sr--
 TACAN AZIMUTH unusable:
 245°-255° byd 20 NM

MARIPOSA-YOSEMITE (MPI)(KMPI) 4 W UTC-8(-7DT) N37°30.65' W120°02.37' **SAN FRANCISCO**
 2254 B NOTAM FILE RIU **L-3B, 9A**
RWY 08-26: H3305X60 (ASPH) S-12 MIRL 0.9% up W **IAP**
RWY 08: PAPI(P2L)—GA 4.0° TCH 36'. Tree. Rgt tfc.
RWY 26: PAPI(P2L)—GA 4.5° TCH 40'. Tree.
SERVICE: S2 **FUEL** 100LL, JET A **LGT** ACTIVATE PAPI Rwy 08 and Rwy 26; MIRL Rwy 08-26—CTAF.
AIRPORT REMARKS: Attended Mon-Fri 1800-0000Z†, Sat-Sun 1800-2200Z†. Fuel avbl 24 hrs with credit card. Parachute Jumping. Birds on and invof arpt. Rwy 08 terrain drops along both sides of twy 45' from rwy edge. Limited parking weekends and holidays.
AIRPORT MANAGER: (209) 966-2143
WEATHER DATA SOURCES: AWOS-3 135.6 (209) 966-2912.
COMMUNICATIONS: CTAF/UNICOM 122.7
 Ⓡ **OAKLAND CENTER APP/DEP CON** 121.25
CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.
RADIO AIDS TO NAVIGATION: NOTAM FILE RIU.
FRIANT (L) VORTACW 115.6 FRA Chan 103 N37°06.27' W119°35.73' 302° 32.3 NM to fld. 2380/17E.

MARKLEEVILLE

ALPINE CO (M45) 3 N UTC-8(-7DT) N38°44.09' W119°46.02' **SAN FRANCISCO**
 5872 TPA-6672(800) NOTAM FILE RNO **L-9A**
RWY 17-35: H4443X50 (ASPH) 1.0% up S
RWY 17: Hill.
RWY 35: Rgt tfc.
AIRPORT REMARKS: Unattended. No snow removal, arpt CLOSED when snow on rwy. Soil conditions off rwy is poor in wet conditions. Call public works for additional information 530-694-2140 extension 0. Large stones along edge of rwy off graded surface. Rwy 17-35 ltd by arpt opr to 4,800 lbs single wheel, 9,600 lbs dual wheel.
AIRPORT MANAGER: 530-694-2140
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.
RADIO AIDS TO NAVIGATION: NOTAM FILE RNO.
MUSTANG (H) VORTACW 117.9 FMG Chan 126 N39°31.88' W119°39.36' 170° 48.0 NM to fld. 5950/16E.
 VORTAC unusable:
 200°-230° byd 30 NM blo 13,000'