

LAKE VILLAGE (C98) 1 NW UTC-6(-5DT) N41°09.00' W87°27.75'

CHICAGO

644 NOTAM FILE HUF

RWY 18-36: 2000X140 (TURF) LIRL

RWY 18: Road.

RWY 36: Road.

SERVICE: S4 LGT ACTIVATE LIRL Rwy 18-36—CTAF.

AIRPORT REMARKS: Attended SR to SS. Deer on and invof arpt. Vehicles on road srndg rwy. Rwy 18-36 width mid 38 ft asph. Rwy end 18 mkg 3 yellow tires/lgts each side. Rwy end 36 mkg 3 yellow tires/lgts each side.

AIRPORT MANAGER: 219-992-9200

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

LAKE WAWASEE SPB (See SYRACUSE on page 139)

LEBANON

BOONE CO (614) 2 SE UTC-5(-4DT) N40°00.44' W86°26.43'

CHICAGO

959 B TPA—1900(941) NOTAM FILE HUF

RWY 18-36: H3600X30 (CONC) S-10.5 LIRL(NSTD) 0.3% up S

RWY 18: Crops.

RWY 36: Thld dspld 200'. Tree.

SERVICE: LGT ACTIVATE LIRL Rwy 18-36—122.8.

AIRPORT REMARKS: Attended irregularly. Ultralights on and invof arpt. Rwy 18-36 has loose gravel and cracks. Rwy 18-36 NSTD LIRL—lights 24' from rwy edge.

AIRPORT MANAGER: 317-281-6791

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Indianapolis Apch at 317-227-5743.


RADIO AIDS TO NAVIGATION: NOTAM FILE HUF.

BRICKYARD (H) (H) VORTACW 116.3 VHP Chan 110 N39°48.88'

W86°22.05' 343° 12.0 NM to fld. 872/1E.

TACAN unusable:

312°-346° byd 25 NM blo 4,000'



LEE BOTTOM (See HANOVER on page 112)

LEO—CEDARVILLE

CEDARVILLE RESERVOIR SPB (IN4) 1 SE UTC-5(-4DT) N41°12.26' W85°00.86'

CHICAGO

781 NOTAM FILE

WATERWAY 03W-21W: 4141X480 (WATER)

AIRPORT MANAGER: (317) 232-0935

COMMUNICATIONS: CTAF 122.9