

BROKEN BOW MUNI/KEITH GLAZE FLD (BBW)(KBBW) 2 N UTC-6(-5DT) N41°26.19' W99°38.53'

OMAHA
L-12H
IAP

2546 B NOTAM FILE BBW
RWY 14-32: H4203X75 (CONC) S-30 MIRL 0.6% up NW
RWY 14: REIL. PAPI(P2L)—GA 3.0° TCH 32'. Road.
RWY 32: PAPI(P2L)—GA 3.0° TCH 41'. Road.

SERVICE: FUEL 100LL, JET A LGT ACTIVATE MIRL and PAPI Rwy 14-32, REIL Rwy 14—CTAF.


AIRPORT REMARKS: Unattended. For svc call numbers listed on notice in terminal building. JET A avbl by prior arrangement. 24 hrs self svc fuel avbl via credit card system for 100LL. Courtesy car and van avbl.

AIRPORT MANAGER: 308-872-2875
WEATHER DATA SOURCES: ASOS 120.0 (308) 872-5354.
COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ DENVER CENTER APP/DEP CON 132.7

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.
RADIO AIDS TO NAVIGATION: NOTAM FILE BBW.

CUSTER COUNTY (L) (L) VORW/DME 108.2 CUZ Chan 19
 N41°29.04' W99°41.34' 135° 3.5 NM to fld. 2842/8E.



BURWELL

CRAM FLD (BUB)(KBUB) 1 SW UTC-6(-5DT) N41°46.65' W99°09.01'

OMAHA
L-12H
IAP

2183 B NOTAM FILE OLU
RWY 15-33: H3900X60 (CONC) S-30, D-30 MIRL 0.3% up SE
RWY 15: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Road.
RWY 33: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Tree.

SERVICE: FUEL 100LL LGT REIL Rwy 15 and 33; PAPI 15 and 33;
 MIRL Rwy 15-33 preset on med intst until 0600Z±; aft 0600Z± actv and incr intst—CTAF.

AIRPORT REMARKS: Unattended. Deer on and invof arpt. Waterfowl on and invof arpt. 24-hr self svc fuel avbl via credit card system. Center pivot irrigation sys rotates thru left side of Rwy 15 apch during irrigation season.

AIRPORT MANAGER: (308) 214-0635
COMMUNICATIONS: CTAF 122.9

Ⓡ DENVER CENTER APP/DEP CON 132.7

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.
RADIO AIDS TO NAVIGATION: NOTAM FILE OLU.

WOLBACH (H) (H) VORTACW 114.8 OBH Chan 95 N41°22.54'
 W98°21.22' 297° 43.2 NM to fld. 2010/7E.
 TACAN azimuth out of service

