

PHILLIPS AAF (APG)(KAPG) A 2 S UTC-5(-4DT) N39°27.93' W76°10.10'

WASHINGTON

45 B NOTAM FILE DCA Not insp.

H-101, 121, L-34F, 361, A

RWY 04-22: H7998X200 (ASPH) PCN 44 F/A/W/T HIRL

DIAP

RWY 22: REIL. PAPI(P4L)—GA 3.0° TCH 49'.

SERVICE: **MILITARY**—LGT ACTVT REIL Rwy 22; PAPI Rwy 22; HIRL Rwy 04-22, when twr clsd by PPR only. **FUEL J8 OIL** O-113-156(Mil)

NOISE: Noise abatement: Noise sensitive area. Use ns abtmt opr procedure.

MILITARY REMARKS: Opr 1100-2300Z‡ Mon-Fri, exc hol. **RSTD** 24 hr PPR all acft. Tran acft ldg at any site other than arpt before SR or 1200Z‡, whichever is later or after SS is prohibited. DSN 298-3483/3074, C410-278-3483/3074.

CAUTION Impact area 1300 yards south of Rwy 04-22 and 2.5 miles southwest of departure end of Rwy 22. Deer haz. Ctc twr 15 min prior to arrival to arrange deer sweep. If twr clsd use extreme caution. **MISC:** ARFF protection not located on afld. ARFF station may not be manned during afld non-opr hrs. Afld signs NSTD or missing. Afld markings faded or missing.

AIRPORT MANAGER: 410-278-4902

COMMUNICATIONS: ATIS 124.425 (Mon-Fri 1100-2300Z‡)

Ⓡ **POTOMAC APP/DEP CON** 125.525 291.625

TOWER 126.15 229.6 241.0 (1300-2100Z‡ Mon-Fri exc holidays, other times PPR.) **GND CON** 121.9

CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc Potomac Apch at 866-429-5882.

AIRSPACE: CLASS D svc 1300-2100Z‡ Mon-Fri exc hol; other times PPR; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIV.

DUPONT (L) (L) VORTAC 114.0 DQO Chan 87 N39°40.69' W75°36.43' 254° 29.0 NM to fld. 70/10W.

VOR unusable:

230°-265° byd 20 NM

TACAN AZIMUTH unusable:

230°-265° byd 20 NM

DME unusable:

230°-265° byd 20 NM

PIER 7 HELIPORT (See BALTIMORE on page 94)

POTOMAC AIRFIELD (See FRIENDLY on page 102)

RIDGELY

GOODEN AIRPARK (RJD)(KRJD) 2 NE UTC-5(-4DT) N38°58.21' W75°51.98'

WASHINGTON

64 B NOTAM FILE DCA

L-34F, 361, A

RWY 12-30: H3214X50 (ASPH) S-28, D-39 LIRL

IAP

RWY 12: REIL. P-line.

RWY 30: REIL. Trees. Rgt tfc.

SERVICE: S4 LGT ACTVT REIL Rwy 12 and Rwy 30; LIRL Rwy 12-30—CTAF.

AIRPORT REMARKS: Unattended. PPR for use of grass surfaces. Birds, deer and wildlife on and infov arpt. Unlimited vehicle access to acft movement areas. Turf areas adjacent to acft movement areas soft when wet. Twy/Aprn pavements are failing with loose aggregate and alligator cracking. Rwy 12-30 thld bars and rwy numbers are half size.

AIRPORT MANAGER: 302-270-2227

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **POTOMAC APP/DEP CON** 124.55

DOVER APP/DEP CON 132.425 (Rwy 30)

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 540-349-7541.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIV.

SMYRNA (L) (L) VORTACW 111.4 ENO Chan 51 N39°13.90'

W75°30.96' 235° 22.7 NM to fld. 15/9W.

TACAN AZIMUTH unusable:

140°-150° byd 36 NM blo 2,000'

200°-300° byd 36 NM blo 3,000'

VOR unusable:


159°-169° blo 3,000 . 325-335 byd 15NM blo 4,900'

DME unusable:

140°-150° byd 36 NM blo 2,000'

200°-300° byd 36 NM blo 3,000'

COMM/NAV/WEATHER REMARKS: UNICOM unmon.



ST MARY'S CO RGNL (See LEONARDTOWN on page 109)