

POTSDAM MUNI/DAMON FLD (PTD)(KPTD) 2 E UTC-5(-4DT) N44°40.60' W74°56.91'

MONTREAL

474 B TPA—1274(800) NOTAM FILE PTD

L-32G

RWY 06-24: H3703X75 (ASPH) S-30 MIRL

IAP

RWY 06: REIL. PAPI(P2L)—GA 3.0° TCH 45'. Tree.

RWY 24: REIL. PAPI(P2L)—GA 3.0° TCH 45'. Tree.

SERVICE: S4 FUEL 100LL, JET A LGT ACTVT REIL Rwy 06 and 24; PAPI Rws 06 and 24; MIRL Rwy 06-24; twy lghts—CTAF.

NOISE: Noise abatement procs in effect—left turn when able departing Rwy 24.

AIRPORT REMARKS: Unattended. Deer on and invof arpt. Expect fit training ops invof arpt. Fuel 24 hr self-serve. Rwy condition not monitored, recommend visual inspection prior to use.

AIRPORT MANAGER: 315-268-1000

WEATHER DATA SOURCES: AWOS-3P 118.325 (315) 265-6106.

COMMUNICATIONS: CTAF/UNICOM 122.8

BOSTON CENTER APP/DEP CON 135.25

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE MSS.

MASSENA (H) TACAN Chan 88 MSS (114.1) N44°54.87' W74°43.36' 228° 17.2 NM to fld. 198/14W.

NDB (MHW) 400 PTD N44°43.40' W74°52.96' 239° 4.0 NM to fld. 360/14W. NOTAM FILE PTD.

NDB unusable:

Byd 20 NM

POUGHKEEPSIE

HUDSON VALLEY RGNL (POU)(KPOU) 4 S UTC-5(-4DT) N41°37.60' W73°53.05'

NEW YORK

164 B TPA—See Remarks ARFF Index—See Remarks NOTAM FILE POU

H-101, 121, L-338, 341

RWY 06-24: H5001X100 (ASPH-GRVD) S-50, D-60, 2D-110

IAP, AD

PCN 42 F/D/W/T HIRL

RWY 06: MALSR. PAPI(P4L)—GA 3.0° TCH 57'. Tree.

RWY 24: REIL. PAPI(P4L)—GA 3.42° TCH 57'. Thld dsplcd 115'. Tree.

RWY 15-33: H2744X100 (ASPH-CONC) S-35, D-45, 2D-80

PCN 26 F/D/W/T MIRL 0.3% up SE

RWY 15: Trees.

RWY 33: REIL. VASI(V4L)—GA 3.75° TCH 64'. Trees.

RWY 07-25: 1358X100 (TURF)

RWY 25: Antenna.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 06: TORA-5001 TODA-5001 ASDA-5001 LDA-5001

RWY 07: TORA-1358 TODA-1358 ASDA-1358 LDA-1358

RWY 15: TORA-2743 TODA-2743 ASDA-2743 LDA-2743

RWY 24: TORA-5001 TODA-5001 ASDA-5001 LDA-4888

RWY 25: TORA-1358 TODA-1358 ASDA-1358 LDA-1358

RWY 33: TORA-2743 TODA-2743 ASDA-2743 LDA-2743

SERVICE: S4 FUEL 100LL, JET A LGT When twr clsd actvt HIRL Rwy 06-24, REIL Rwy 24, MALSR Rwy 06—CTAF.

NOISE: Noise abatement procedures in effect, ctc arpt manager for details.

AIRPORT REMARKS: Attended 1200-0230Z. Deer and birds on and invof arpt. Rwy 15-33 CLOSED to air carrier acft. Rwy 07-25 CLOSED nghts, during instrument meteorological conditions and from Nov 1-Apr 15. Rwy 15-33 clsd to sked acr ops with more than 9 pax seats and non sked acr ops with more than 30 pax seats exp for taxi. Ctc FBO during business hrs at 845-849-3770 for after hrs fuel svc. TPA—1197(1034) small acft 1997(1834) large acft. Rwy 33 use of VASI rstd to category A acft only. Rwy 07-25 rstd to acft less than 12,500 lbs. Class IV, ARFF Index A. PPR 24 hrs for air carrier ops with more than 30 passenger seats call arpt manager 845-463-6000. Index B coverage is provided. Twy B-1, Twy G T-hangar taxilane, and Twy J t-hangar taxilane clsd to air carrier acft. Ground soft in tie down areas. Rwy 06 touch and go lndg and practice apchs prohibited due to obscd line of sight fm ATCT. Ldg fee for multi-engine acft.

AIRPORT MANAGER: 845-463-6000

WEATHER DATA SOURCES: ASOS 126.75 (845) 462-0648. LAWRS.

COMMUNICATIONS: CTAF 124.0 ATIS 126.75 UNICOM 122.95

Ⓡ **NEW YORK APP/DEP CON** 132.75

TOWER 124.0 (1200-0300Z. 15 May-14 Sept, 1200-0200Z. 15 Sept-14 May) **GND CON** 121.8 **CLNC DEL** 121.8

CLEARANCE DELIVERY PHONE: For CD when ATCT clsd ctc New York Apch at 516-683-2448 or 121.8.

AIRSPACE: CLASS D svc 1200-0300Z. 15 May-14 Sep, 1200-0200Z. 15 Sep-14 May; other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE ISP.

KINGSTON (L) (L) VOR/DME 117.6 IGN Chan 123 N41°39.93' W73°49.33' 242° 3.6 NM to fld. 582/12W.

VOR portion unusable:

045°-050° byd 35 NM blo 4,300'

070°-140° byd 30 NM blo 3,400'

ILS 111.3 I-POU Rwy 06. Class IA. Unmonitored when ATCT clsd.

