

LAURIER**AVEY FLD** (69S) 2 SW UTC-8(-7DT) N48°59.90' W118°13.36'

SEATTLE

1655 NOTAM FILE SEA

RWY 17-35: 1975X40 (GRVL)**RWY 17:** Trees.**RWY 35:** Trees.**AIRPORT REMARKS:** Unattended. Vehicles and animals on and invof rwy. Rwy 17 marked with retro-reflective devices.

Helicopter operations on airport during fire season. Shoulders very soft and rough both sides of rwy. Canadian and U.S. customs avbl on hwy to the west. U.S. based acft should park on the U.S. side of ramp, south, and Canadian based acft should park on north side of ramp.

AIRPORT MANAGER: 509-684-2240**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**LEAVENWORTH****LAKE WENATCHEE STATE** (27W) 14 NW UTC-8(-7DT) N47°49.16' W120°43.19'

SEATTLE

1939 NOTAM FILE SEA

RWY 09-27: 2473X100 (TURF) 0.4% up W**RWY 09:** Road.**RWY 27:** Road.**AIRPORT REMARKS:** Unattended. CLOSED 1 Oct-1 Jun. Pedestrians, vehicles and animals on and invof rwy. Two windsocks, one at each rwy end. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Rwy marked with reflectors dur dates arpt is open.**AIRPORT MANAGER:** (360) 618-2477**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**LIND** (ØSØ) 2 NE UTC-8(-7DT) N46°58.61' W118°35.23'

SEATTLE

1507 B NOTAM FILE SEA

RWY 05-23: H3197X50 (ASPH) HIRL**RWY 23:** Hill.**SERVICE:** LGT ACTIVATE HIRL Rwy 05-23-CTAF.**AIRPORT REMARKS:** Unattended. East end of rwy has 800' by 50' dirt graded safety area. Rwy 05-23 markings faded.**AIRPORT MANAGER:** 509-677-3241**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MWH.**MOSES LAKE (H) (H) VORW/DME** 115.0 MWH Chan 97 N47°12.65' W119°19.01' 097° 33.0 NM to fld. 1193/18E.**LITTLE GOOSE LOCK AND DAM** (See STARBUCK on page 228)**LOPEZ****FISHERMANS BAY SPB** (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08'

SEATTLE

00 NOTAM FILE SEA

WATERWAY 05W-23W: 3000X150 (WATER)**WATERWAY 05W:** Rgt tfc.**SEAPLANE REMARKS:** Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay.**AIRPORT MANAGER:** 360-468-4116**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Whidbey Apch at 360-257-3310.**LOPEZ ISLAND** (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26'

SEATTLE

209 B NOTAM FILE SEA

RWY 16-34: H2905X61 (ASPH-GRVD) S-12.5 MIRL 1.6% up N**RWY 16:** REIL. PAPI(P2L)—GA 4.0° TCH 43'. Trees. Rgt tfc.**RWY 34:** REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees.**AIRPORT REMARKS:** Unattended. Rwy 16-34 soft shoulders and thlds.**AIRPORT MANAGER:** 360-468-4116**COMMUNICATIONS:** CTAF 128.25**CLEARANCE DELIVERY PHONE:** For CD ctc Whidbey Apch at 360-257-3310.