

DURANT RGNL/EAKER FLD (DUA)(KDUJA) 3 SW UTC-6(-5DT) N33°56.38' W96°23.70'

DALLAS-FT WORTH

699 B NOTAM FILE DUA

H-6H, L-17C

RWY 17-35: H6800X100 (ASPH) S-35, D-50 PCN 24 F/B/X/U MIRL

IAP

RWY 17: ODALS. PAPI(P4L)—GA 3.0° TCH 43'. Trees.

RWY 35: PAPI(P4L)—GA 3.0° TCH 42'.

SERVICE: S4 **FUEL** 100LL, **JET A** **LGT** Actvt ODALS Rwy 17; MIRL Rwy 17-35; twy lgt—CTAF. PAPI Rwy 17 and 35 opr consly.

AIRPORT REMARKS: Attended Mon-Fri 1300-0100Z; Sat-Sun 1300-0100Z; Avbl H24 O/R. Extsv student trng invof arprt and over Lake Texoma. After hrs call 580-579-5024. 100LL avbl 24 hrs with automated credit card system. For fuel aft hrs call 580-579-5024. 372' twr 2.5 miles N of arprt.

AIRPORT MANAGER: 580-920-0574

WEATHER DATA SOURCES: AWOS-3 124.175 (580) 931-3790.

COMMUNICATIONS: CTAF/UNICOM 123.05

® **FORT WORTH CENTER APP/DEP CON** 124.75

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.


RADIO AIDS TO NAVIGATION: NOTAM FILE DUA.

TEXOMA (L) DME 114.3 URH Chan 90 N33°56.65' W96°23.51' at fld. 682/OE.

DME unusable:

207°-240° byd 35 NM blo 2,500'

335°-350° byd 35 NM blo 2,500'



EL RENO

EL RENO (99F) 2 SW UTC-6(-5DT) N35°31.00' W97°58.77'

DALLAS-FT WORTH

1395 NOTAM FILE MLC

RWY 17-35: 2600X100 (TURF)

RWY 17: Tree. Rgt tfc.

RWY 35: Bldg.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z; E/W Twy marked with orange 'L' shaped markers, do not land on twy.

AIRPORT MANAGER: 405-262-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oke City Apch at 405-681-5683.

