

AMARILLO**BUFFALO** (1E7) 9 S UTC-6(-5DT) N35°03.83' W101°52.66'

DALLAS-FT WORTH

3640 B NOTAM FILE FTW

RWY 02-20: 6200X150 (TURF) LIRL(NSTD)**RWY 02:** Fence.**RWY 20:** Tree. Rgt tfc.**RWY 08-26:** 1600X102 (TURF)**RWY 08:** P-line.**RWY 26:** Road.**SERVICE:** LGT Dusk-0700Z±. Rwy 02-20 Nonstd LIRL; first 3000' north end of rwy lgtd. Thr lghts at north end only.**AIRPORT REMARKS:** Attended irregularly. Radio controlled model acft act north end of arpt. Rwy 02-20 and Rwy 08-26 not mntnd, not mowed publd len and wid.**AIRPORT MANAGER:** (806) 236-1109**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.**PALO DURO** (1E4) 3 S UTC-6(-5DT) N35°08.62' W101°50.35'

DALLAS-FT WORTH

3639 NOTAM FILE FTW

RWY 17-35: 3700X50 (TURF-GRVL)**RWY 17:** P-line.**RWY 35:** Fence.**AIRPORT REMARKS:** Unattended. Arpt fenced, gates locked, no aces. Rwy not suitable for acft. Arpt hazus for tsnts; rwy not mkd or defined; 63' transmission line acrs thr Rwy 17. Rwy 17-35 soft when wet on S end; loose grvl on rwy, vegetation on rwy.**AIRPORT MANAGER:** 806-376-5853**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.