


CEDARVILLE (059) 2 N UTC-8(-7DT) N41°33.22' W120°09.94'
 4623 B NOTAM FILE RNO
RWY 02-20: H4415X50 (ASPH) S-12.5 MIRL 1.2% up S
RWY 02: Thld dsplcd 120'. Road.
SERVICE: LGT ACTIVATE MIRL Rwy 02-20—CTAF.
AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: 530-233-6412
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.
RADIO AIDS TO NAVIGATION: NOTAM FILE LKV.
LAKEVIEW (H) (H) VORTACW 112.0 LKV Chan 57 N42°29.57'
 W120°30.43' 146° 58.4 NM to fld. 7465/19E.

KLAMATH FALLS
 L-11A



CHARLES M SCHULZ – SONOMA CO (See SANTA ROSA on page 229)

CHEMEHUEVI VALLEY (49X) 4 N UTC-8(-7DT) N34°31.73' W114°25.92'
 638 B NOTAM FILE RAL
RWY 16-34: H5000X75 (ASPH) S-12 MIRL
SERVICE: LGT ACTIVATE MIRL Rwy 16-34—CTAF.
AIRPORT REMARKS: Unattended. Rwy 16-34 cracks in rwy surface and rwy edges failing.
AIRPORT MANAGER: 760-858-1116
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Los Angeles ARTCC at 661-575-2079.
RADIO AIDS TO NAVIGATION: NOTAM FILE EED.
NEEDLES (H) (H) VORTAC 115.2 EED Chan 99 N34°45.96'
 W114°28.45' 157° 14.4 NM to fld. 620/15E.
VORTAC unusable:
 100°-130° byd 27 NM blo 6,600'
 170°-220° byd 20 NM blo 5,800'
 220°-280° byd 35 NM blo 6,800'
TACAN AZIMUTH & DME unusable:
 165°-220° byd 20 NM blo 8,000'
 165°-220° byd 30 NM blo 12,000'

PHOENIX
 H-41, L-5A, 7E

