


CAVALIER MUNI (2C8) 1 SW UTC-6(-5DT) N48°47.02' W97°37.92'

TWIN CITIES

892 B NOTAM FILE GFK

RWY 16-34: H3299X60 (ASPH) S-12.5 MIRL**RWY 16:** PAPI(P2L)—GA 3.0° TCH 26'.**RWY 34:** PAPI(P2L)—GA 4.0° TCH 36'. Bldg.**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE and incr ints PAPI on Rwy 16 and Rwy 34; MIRL Rwy 16-34—CTAF. Rwy 34 PAPI unusbl beyond 5 degs right of cntrln.**AIRPORT REMARKS:** Attended on call. Self svc fuel avbl 24 hrs with credit card. Confirm snow removal with arpt manager after winter storm. Power plant and airframe repairs call 507-530-5638. Rwy 34 +31' P-line 1300' from thld on centerline, apch ratio 35:1. Rwy 16 +45' marked P-line 1920' from thld on centerline, apch ratio 38:1. Helipad located south edge of apron.**AIRPORT MANAGER:** 701-520-8631**WEATHER DATA SOURCES:** AWOS-3 118.275 (701) 265-8050.**COMMUNICATIONS:** CTAF/UNICOM 122.8**DEVILS LAKE RCO 122.3 (GRAND FORKS RADIO)**Ⓡ **MINNEAPOLIS CENTER APP/DEP CON 132.15****CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.L-146
IAP**COLUMBUS MUNI (D49) 1 SW UTC-6(-5DT) N48°53.96' W102°47.54'**


BILLINGS

1931 NOTAM FILE GFK

RWY 07-25: 2560X100 (TURF) RWY LGTS(NSTD)**RWY 07:** APAP(PNIL)—GA 5.0° TCH 13'.**RWY 25:** APAP(PNIR)—GA 5.0° TCH 13'. Thld dsplcd 208'. Road.**SERVICE:** LGT Rwy 07-25 NSTD rwy lgts. Rwy 07-25 APAP left and right sides. Rwy 07-25 APAP—plywood panels lgt d ngt. Rwy 07-25 has threshold end lgts with reflector side panels for ngt use.**AIRPORT REMARKS:** Unattended. No snow removal avbl winter months, confirm winter conditions with arpt manager 701-339-0355, 701-939-5038 or 701-339-8420. Rwy 25 has 5' ditch 30' from threshold. Test arpt for rwy marking system. Rwy 07-25 marked with faded black/white edge and end panels.**AIRPORT MANAGER:** (701) 216-0030**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**COOPERSTOWN MUNI (S32) 2 SE UTC-6(-5DT) N47°25.37' W98°06.35'**

TWIN CITIES

1424 NOTAM FILE GFK

RWY 13-31: H3500X60 (ASPH) S-12.5 MIRL**RWY 13:** PAPI(P2L)—GA 3.0° TCH 25'.**RWY 31:** PAPI(P2L)—GA 3.0° TCH 25'.**SERVICE:** FUEL 100LL LGT MIRL on Rwy 13-31 preset on low ints, to increase ints and ACTIVATE PAPI Rwy 13 and Rwy 31—CTAF.**AIRPORT REMARKS:** Attended Oct-Apr on call, May-Sep Mon-Fri 1400-2300Z±. Self svc 100LL fuel credit card svc 24 hrs avbl. Confirm winter conditions and snow removal with arpt manager on 701-789-0666. Possible birds and deer invof arpt. For agri svc 701-789-0666 Apr-Oct. Helicopter ldg area located east apron edge; snow removal irregular.**AIRPORT MANAGER:** 701-789-0666**WEATHER DATA SOURCES:** AWOS-3 118.750 (701) 797-2566.**COMMUNICATIONS:** CTAF 122.9**JAMESTOWN RCO 122.2 (GRAND FORKS RADIO)**Ⓡ **MINNEAPOLIS CENTER APP/DEP CON 132.15****CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE JMS.**JAMESTOWN (L) (L) VORV/DME 114.5 JMS Chan 92 N46°55.97' W98°40.73' 034° 37.6 NM to fld. 1493/4E.**L-146
IAP