

WILLITS

ELLS FLD/WILLITS MUNI (O28) 3 NW UTC-8(-7DT) N39°27.08' W123°22.34'

SAN FRANCISCO

2066 B NOTAM FILE OAK

L-2G

RWY 16-34: H2705X75 (ASPH) S-30 MIRL 1.4% up N

IAP

RWY 16: Trees.

RWY 34: PAPI(P2L)—GA 3.0° TCH 21'. Trees. Rgt tfc.

SERVICE: S2 FUEL 100LL LGT Rotating bcn OTS. ACTIVATE MIRL Rwy 16-34, PAPI Rwy 34—CTAF.

AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Deer and turkey on and invof rwy. Acft not visible from opposite end of the rwy.

AIRPORT MANAGER: (707) 459-1562

COMMUNICATIONS: CTAF/UNICOM 122.8

① OAKLAND CENTER APP/DEP CON 132.2

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE UKI.

MENDOCINO (H) (H) VORTACW 112.3 ENI Chan 70 N39°03.19' W123°16.46' 333° 24.3 NM to fld. 2985/16E.

WILLOWS/GLENN CO (WLW)(KWLW) 1 W UTC-8(-7DT) N39°30.95' W122°13.04'

SAN FRANCISCO

141 B NOTAM FILE RIU

L-2G

RWY 16-34: H4125X100 (ASPH) S-38, D-53 MIRL

IAP

RWY 16: Road. Rgt tfc.

RWY 34: VASI(V4L)—GA 3.0° TCH 31'.

RWY 13-31: H3788X60 (ASPH) S-12

RWY 13: Trees. Rgt tfc.

RWY 31: Thld dspcd 243'.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 16-34 and VASI Rwy 34—CTAF.


AIRPORT REMARKS: Attended 1530-2330Z±. Fuel 24 hr card lock.

AIRPORT MANAGER: 530-934-6530

COMMUNICATIONS: CTAF/UNICOM 122.8

① OAKLAND CENTER APP/DEP CON 132.2

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.



WOODLAKE (O42) 2 S UTC-8(-7DT) N36°23.93' W119°06.41'

SAN FRANCISCO

425 B TPA—1225(800) NOTAM FILE RIU

RWY 07-25: H2203X50 (ASPH-TRTD)

RWY 07: Trees.

RWY 25: Bldg.

SERVICE: FUEL 100LL

AIRPORT REMARKS: Unattended. Arpt not approved for ngt use. Gross pavement strength provided by arpt manager, 8000 lbs.

AIRPORT MANAGER: 559-564-8055

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.