

MARYSVILLE, CALIFORNIA

HI-TACAN Z RWY 33

TACAN BAB Chan 23	APCH CRS 317°	Rwy ldg 12,001
		TDZE 105
		Arprt Elev 113


JAL-771 (USAF)

BEALE AFB (KBAB)

V * When ALS inop, increase CAT CDE vis to 1 1/4 miles.
 ** Circling not authorized E of Rwy 15-33

ALSF-1  MISSED APPROACH: Climb to 3600, intercept BAB TACAN R-326 to HAPAK and hold.

ATIS* 124.55 273.5	NORCAL APP CON 125.4 259.1	TOWER* 119.4 284.75	GND CON 121.6 257.75
-----------------------	-------------------------------	------------------------	-------------------------



3600 ↑ BAB R-326	HAPAK BAB 16	COLSO R-137 15	ELEV 113	TDZE 105
TACAN	EGUYO 1.5	SHERI 6	3200	BCN 240
2.2	1800	317°	3200	TWR 274
.5	4.5 NM	317°	3200	13,001 x 300
			≤ 3.09°	33
			TCH 51	317° to TACAN
CATEGORY	C	D	E	
S-33*	540/40	435	(500-3/4)	
CIRCLING**	600-1 1/2 487 (500-1 1/2)	680-2 567 (600-2)	840-2 1/2 727 (800-2 1/2)	

HIRL all Rwys

MARYSVILLE, CALIFORNIA

39°08'N - 121°26'W

BEALE AFB (KBAB)

Amdt 5 20JUL17

HI-TACAN Z RWY 33

SW-2, 27 JAN 2022 to 24 FEB 2022

SW-2, 27 JAN 2022 to 24 FEB 2022