

SIDNEY MUNI (SCA)(KSCA) 3 S UTC-5(-4DT) N40°14.48' W84°08.87'

1044 B TPA—1844(800) NOTAM FILE DAY

RWY 10-28: H5013X75 (ASPH) MIRL

RWY 10: REIL. PAPI(P2L)—GA 3.0° TCH 42'. Crops.

RWY 28: REIL. PAPI(P2L)—GA 3.0° TCH 36'. Crops.

RWY 05-23: H2981X50 (ASPH)

RWY 05: Trees.

RWY 23: Crops.

SERVICE: S4 **FUEL** 100LL, JET A+ **OX1** **LGT** ACTIVATE REIL Rwy 10 and Rwy 28; MIRL Rwy 10-28—CTAF. PAPI Rwy 10 and Rwy 28 opr consly.

AIRPORT REMARKS: Attended Mon—Sat 1300-2300Z±. Fuel avbl H24 via credit card.

AIRPORT MANAGER: 937-492-9794

WEATHER DATA SOURCES: AWOS-3 120.425 (937) 492-3683.

COMMUNICATIONS: CTAF/UNICOM 123.05

Ⓡ **COLUMBUS APP/DEP CON** 118.425

CLEARANCE DELIVERY PHONE: For CD etc Columbus Apch at 614-338-8537.

RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.

ROSEWOOD (H) (H) VORTACW 117.5 ROD Chan 122 N40°17.27' W84°02.59' 245° 5.6 NM to fld. 1080/5W.

TACAN AZIMUTH unusable:

000°-120°

125°-135°

VOR unusable:

125°-135°

DETROIT
H-10G, L-27E
IAP

SPORTYS N39°04.60' W84°12.92' NOTAM FILE DAY.

NDB (MHW) 245 PWF at Clermont Co. 850/4W.

NDB unusable:

Byd 15 NM

CINCINNATI
L-27E

SPRINGFIELD/BECKLEY MUNI (SGH)(KSGH) P (ANG) 5 S UTC-5(-4DT) N39°50.42' W83°50.41' **CINCINNATI**

1051 B TPA—See Remarks NOTAM FILE SGH

RWY 06-24: H9010X150 (ASPH-CONC-GRVD) S-50, D-60

PCN 60 R/B/W/T HIRL

RWY 06: REIL. PAPI(P4L)—GA 3.0° TCH 43'. Trees.

RWY 24: SSALR. PAPI(P4L)—GA 3.0° TCH 60'. Tree.

RWY 15-33: H5498X100 (ASPH) S-12 MIRL

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 36'. Crops.

RWY 33: REIL. PAPI(P4L)—GA 3.0° TCH 37'. Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 06: TORA-9009 TODA-9009 ASDA-9009 LDA-9009

RWY 15: TORA-5499 TODA-5499 ASDA-5499 LDA-5499

RWY 24: TORA-9009 TODA-9009 ASDA-9009 LDA-9009

RWY 33: TORA-5499 TODA-5499 ASDA-5499 LDA-5499

SERVICE: S4 **FUEL** 100LL, JET A, A+ **OX1, 4** **LGT** ACTIVATE SSALR

Rwy 24; REIL Rwy 06, 13 and 33; HIRL Rwy 06-24; MIRL Rwy

15-33—CTAF. PAPI Rwy 06, 24, 15 and 33 opr consly. ACTIVATE

wind cone—CTAF. Wind tee OTS indef. Rwy 15 PAPI unusbl byd 9°

right of cntrln. Rwy 24 ALS unmon indefly.

NOISE: Noise abatement: Avoid overflying Yellow Springs 2 NM SW blw 4000 ft.

AIRPORT REMARKS: Attended Mon-Fri 1230-2300Z±, Sat-Sun

1400-2200Z±. Ocnl deer, birds and otr wildlife on and infov arpt. Hvy bird activity drg fall and winter months. FBO svcs

avbl on freq 120.7. Rwy 24 is pref wind rwy 10 kt or less. Avoid overflying ANG ramp. Rwy 06-24 980' concrete NE

end, 1200' concrete SW end. TPA—2100 (1049), ohd TPA 2600 (1549).

AIRPORT MANAGER: 937-325-6108

WEATHER DATA SOURCES: AWOS-3PT 134.975 (937) 324-4532.

COMMUNICATIONS: CTAF/UNICOM 122.95

Ⓡ **COLUMBUS APP/DEP CON** 118.85 269.275

CLEARANCE DELIVERY PHONE: For CD etc Columbus Apch at 614-338-8537.

RADIO AIDS TO NAVIGATION: NOTAM FILE DAY.

(T) **TACAN** Chan 65 XSF (133.8) N39°50.29' W83°50.44' at fld. 1052/4W. unmonitored when twr clsd. No

NOTAM MP: 1330-1530Z± Thu.

TACAN AZ unusable:

090°-115° byd 15 NM

(T) **DME** 113.2 SGH Chan 79 N39°50.19' W83°50.70' at fld. 1046/0W. NOTAM FILE SGH.

DME unusable:

150°-160° byd 14 NM blo 5,000'

