

MONTPELIER N44°05.13' W72°26.96' NOTAM FILE MPV.

MONTREAL

(H) (H) **ABVOR/DME** 116.9 MPV Chan 116 342° 8.6 NM to Edward F Knapp State. 2086/16W.

L-32G

RCO 122.2 (BURLINGTON RADIO)**RCO** 122.6 (BURLINGTON RADIO)**MORRISVILLE—STOWE STATE** (MVL)(KMVL) 2 SW UTC-5(-4DT) N44°32.06' W72°36.84'

MONTREAL

733 B NOTAM FILE MVL

L-32G

RWY 01-19: H3700X75 (ASPH) S-25 PCN 12 F/A/X/T HIRL

IAP

0.5% up N

RWY 01: REIL. P-line.**RWY 19:** REIL. PAPI(P2L)—GA 3.5° TCH 31'.**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** ACTIVATE REIL Rwy 01 and Rwy 19, PAPI Rwy 19, HIRL Rwy 01-19—CTAF.**AIRPORT REMARKS:** Attended 1300-2300Z. For fuel and svcs after hrs and information call 802-253-2332. After hrs self-serve fuel kiosk does not accept Mastercard. Rwy conditions may not be monitored or reported when the arpt is unattended. Rwy 01 glider opr are right traffic. 3' swales middle 1/3 of rwy on east and west sides outside of rwy safety area. Cold temperature airport. Altitude correction required at or below -20C.**AIRPORT MANAGER:** (802) 253-2332**WEATHER DATA SOURCES:** ASOS 135.625 (802) 888-7934.**COMMUNICATIONS:** CTAF/UNICOM 122.8**BOSTON CENTER APP/DEP CON** 135.7**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BTV.**BURLINGTON (L) (L) VOR/DME** 117.5 BTV Chan 122 N44°23.83'

W73°10.96' 086° 25.8 NM to fld. 417/15W.

VOR unusable:


075°-132° byd 30 NM blo 9,000'

133°-165° byd 30 NM blo 8,000'

DME unusable:

075°-132° byd 30 NM blo 9,000'

133°-165° byd 30 NM blo 8,000'

**NEWPORT****NORTHEAST KINGDOM INTL** (EFK)(KEFK) 3 SW UTC-5(-4DT) N44°53.29' W72°13.72'

MONTREAL

934 B LRA NOTAM FILE BTV

H-11D, L-32H

RWY 18-36: H5301X100 (ASPH) S-30, D-44 PCN 33 F/D/X/T MIRL

IAP

RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 43'. Thld dspcd 299'.**RWY 36:** REIL. PAPI(P4L)—GA 3.0° TCH 44'. Pole.**RWY 05-23:** H3996X100 (ASPH) S-30, D-44**RWY 05:** Trees.**RWY 23:** Pole.**SERVICE:** S4 **FUEL** 100LL, JET A+ **LGT** ACTVT PAPI Rwy 18 and 36;

MIRL Rwy 18-36—CTAF.


AIRPORT REMARKS: Attended 1400-2200Z. Fuel 24/7 self serve. Mobile fuel vehicle when attended. Rwy conditions may not be monitored or reported when the arpt is unattended. Gulls on and in vicinity of arpt. Cold temperature restricted airport. Altitude correction required at or below -32C.**AIRPORT MANAGER:** 802-334-5001**WEATHER DATA SOURCES:** AWOS-3P 118.275 (802) 334-4427.**COMMUNICATIONS:** CTAF/UNICOM 122.8**NEWPORT RCO** 122.5 (BURLINGTON RADIO)® **BOSTON CENTER APP/DEP CON** 135.7**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BML.**BERLIN (H) DME** 116.55 BML Chan 112(Y) N44°38.01' W71°11.17' 289° 47.1 NM to fld. 1730/OE.

DME unusable:

080t-125t blo 10,000'

188t-198t blo 10,000'

275t-292t blo 10,000'

**NORTHEAST KINGDOM INTL** (See NEWPORT on page 329)