


**DANIELSON** (LZD)(KLZD) 2 NW UTC-5(-4DT) N41°49.19' W71°54.06'  
238 B NOTAM FILE BDR  
RWY 13-31: H2700X75 (ASPH) S-29 MIRL

NEW YORK  
L-33C, 34J  
IAP

RWY 13: Tree.  
RWY 31: REIL. Tree.  
SERVICE: S4 FUEL 100LL  
AIRPORT REMARKS: Unattended. Parachute Jumping. Extsv paja SR-SS  
May-Oct. Gldr actvy on & invof arpt. Deer on & invof arpt. Self svc  
fuel, credit card rqrd: Visa, Mastercard. Ldg fee for business,  
corporate & revenue producing acft.  
AIRPORT MANAGER: 860-982-2443  
WEATHER DATA SOURCES: AWOS-3 119.125 (860) 779-7251.  
COMMUNICATIONS: CTAF/UNICOM 123.0  
PROVIDENCE APP/DEP CON 123.675 (Sun-Fri 1030-0530Z, Sat  
1030-0500Z) other times ctc  
BOSTON CENTER APP/DEP CON 124.85  
CLEARANCE DELIVERY PHONE: For CD ctc Providence Apch at  
401-738-8945, when Apch clsd ctc Boston ARTCC at  
603-879-6859.  
RADIO AIDS TO NAVIGATION: NOTAM FILE BDR.  
PUTNAM (H) (H) VORW/DME 117.4 PUT Chan 121 N41°57.33'  
W71°50.65' 211° 8.5 NM to fld. 652/14W.  
DME unusable:  
265°-301° byd 36 NM blo 3,000'



**EAST HADDAM**

**GOODSPEED** (42B) 1 SE UTC-5(-4DT) N41°26.74' W72°27.34'  
9 NOTAM FILE BDR  
RWY 14-32: H2120X50 (ASPH) S-8 LIRL

NEW YORK

RWY 14: Trees.  
RWY 32: Trees.  
SERVICE: LGT Arpt lgts opr 24 hrs.  
AIRPORT REMARKS: Unattended. Caution for deer, birds and waterfowl on and invof arpt. Deer occasionally on rwy at ngt.  
Overnight parking fee. Ldg fee.  
AIRPORT MANAGER: (860) 615-9068  
COMMUNICATIONS: CTAF/UNICOM 122.8  
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2449.

WATERWAY 16W-34W: 4500X1000 (WATER)  
WATERWAY 16W: Bridge.  
WATERWAY 34W: Hill.

**ELLINGTON** (7B9) 2 N UTC-5(-4DT) N41°55.53' W72°27.43'  
253 NOTAM FILE BDR  
RWY 01-19: H1800X50 (ASPH) S-9 LIRL(NSTD)

NEW YORK

RWY 01: Trees.  
RWY 19: Trees.  
SERVICE: S4 FUEL 100LL LGT Dusk-0500Z. NSTD LIRL Rwy 01-19 opr dusk-0500Z, after 0500Z for NSTD LIRL  
Rwy 01-19 call 860-871-2054.  
AIRPORT REMARKS: Attended 1300-2300Z. Parachute Jumping. Extensive helicopter training ops. Acft tfc pat on E side of  
arpt only (1250' MSL). Hel tfc pat on W side of arpt only (1000' MSL). Rwy 01-19 NSTD LIRL due to spacing. Hangars  
east of rwy penetrate part 77 (7:1 side slopes) Rwy 19 apch end. Rwy 01-19 markings faded.  
AIRPORT MANAGER: 860-614-1854  
COMMUNICATIONS: CTAF/UNICOM 123.0  
CLEARANCE DELIVERY PHONE: For CD ctc Yankee Apch at 860-386-3597

**GOODSPEED** (See EAST HADDAM on page 35)