

RAVENNA**PORTAGE CO** (POV)(KPOV) 3 N UTC-5(-4DT) N41°12.61' W81°15.10'

1198 B NOTAM FILE CLE

RWY 09-27: H3499X75 (ASPH) MIRL**RWY 09:** REIL. Trees.**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 43'. Ground.**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** Actvt REIL Rwy 09 & 27; PAPI Rwy 27; MIRL Rwy 09-27—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1300-2200Z†. Unatndd all major hols. Deer on & invof arpt. 100LL avbl H24 self ser.

Paraglider ops by permit only. All areas off rwy sfc soft when wet or thawing.

AIRPORT MANAGER: 330-298-3277**WEATHER DATA SOURCES:** AWOS-3 118.675 (330) 298-9353.**COMMUNICATIONS:** CTAF/UNICOM 123.05Ⓡ **CLEVELAND APP/DEP CON** 118.6 (1100-0500Z‡)Ⓡ **CLEVELAND CENTER APP/DEP CON** 120.6 (0500-1100Z‡) ctc Cleveland ARTCC at 440-774-0223.

CLNC DEL 125.65

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CAK.**AKRON (L) (L) VORW/DME** 114.4 ACO Chan 91 N41°06.47' W81°12.09' 344° 6.5 NM to fld. 1197/4W.

DME unusable:

Byd 10 NM

DETROIT

L-30G

IAP

RED STEWART AIRFIELD (See WAYNESVILLE on page 317)**RICHARD DOWNING** (See COSHOCTON on page 273)**RICKENBACKER INTL** (See COLUMBUS on page 272)**ROSEWOOD** N40°17.27' W84°02.59' NOTAM FILE DAY.(H) (H) **VORTACW** 117.5 ROD Chan 122 245° 5.6 NM to Sidney Muni. 1080/5W.

TACAN AZIMUTH unusable:

000°-120°

125°-135°

VOR unusable:

125°-135°

DETROIT

H-10G, L-27E

ROSS CO (See CHILLICOTHE on page 264)**RUHE'S** (See LEIPSIC on page 288)**ST CLAIRSVILLE****ALDERMAN** (2P7) 3 SW UTC-5(-4DT) N40°03.41' W80°57.79'

1187 B NOTAM FILE CLE

RWY 01-19: H2840X50 (ASPH) LIRL(NSTD) 0.9% up N**RWY 01:** Trees.**RWY 19:** Trees.**SERVICE:** **LGT** ACTVT NSTD LIRL Rwy 01-19—123.3 or call amgr. ACTVT abn—123.3 or call amgr. Rwy 01-19 nstd LIRL due to 15 ft fm edge of pavement.**AIRPORT REMARKS:** Attended 1300Z†-dusk. Ocnl deer, birds and otr wildlife on and invof arpt. Rwy 01-19 surface is weathered with some raveling, med block cracking throughout. South half of ramp poor cond due to broken pavement. Rwy 01-19 nstd basic due to nrs and sml cntrln with nstd spacing. Ldg fee.**AIRPORT MANAGER:** 740-695-0908**COMMUNICATIONS:** BELLAIRE RCO 117.1T (CLEVELAND RADIO)**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0226/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLE.**BELLAIRE (H) (H) VORW/DME** 117.1 AIR Chan 118 N40°01.02' W80°49.03' 297° 7.1 NM to fld. 1307/7W.

DETROIT

L-29B

IAP