

**LAKE PLACID** (LKP)(KLP) 1 SE UTC-5(-4DT) N44°15.87' W73°57.71'

MONTREAL

1747 NOTAM FILE BTV

L-32G

**RWY 14-32:** H4196X60 (ASPH) S-8 PCN 24 F/B/X/T MIRL

IAP, AD

**RWY 14:** PAPI(P2L)—GA 3.5° TCH 51'. Trees.**RWY 32:** Thld dsplcd 1140'. Trees.**SERVICE:** S4 **FUEL** 100LL, **JET A** **LGT** ACTIVATE PAPI Rwy 14, MIRL Rwy 14-32 and twy lgts—CTAF.**AIRPORT REMARKS:** Attended May-Sep 1300-2100Z±, Oct-Apr 1300-2100Z±. Extensive glider activity. Mountains on both apchs 1-5 miles from rwy ends. 24 hrs advanced notice required for all Jet A svcs after posted business hrs. Cold temperature airport. Altitude correction required at or below -32C. Rwy 14 PAPI unusable byd 3 NM.**AIRPORT MANAGER:** 518-523-2473**COMMUNICATIONS:** CTAF/UNICOM 122.8**BOSTON CENTER APP/DEP CON** 120.35**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BTV.**BURLINGTON (L) (L) VORW/DME** 117.5 BTW Chan 122 N44°23.83' W73°10.96' 272° 34.5 NM to fld. 417/15W.

VOR unusable:


075°-132° byd 30 NM blo 9,000'

133°-165° byd 30 NM blo 8,000'

DME unusable:

075°-132° byd 30 NM blo 9,000'

133°-165° byd 30 NM blo 8,000'

**LANCASTER****BUFFALO-LANCASTER RGNL** (BQR)(KBQR) 3 NE UTC-5(-4DT) N42°55.32' W78°36.72'

DETROIT

752 B TPA-1552(800) NOTAM FILE BUF

L-31E

**RWY 09-27:** H3199X75 (ASPH) MIRL**RWY 09:** REIL. PAPI(P2R)—GA 3.0° TCH 40'. Fence.**RWY 27:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Fence.**SERVICE:** S6 **FUEL** 100LL **LGT** Activate MIRL Rwy 09-27; REIL Rwy 09-27 & PAPI Rwy 09-27—CTAF. Rwy 09 PAPI unusbl byd 3 deg right of RCL. Rwy 27 PAPI unusbl byd 5 deg left of RCL.**AIRPORT REMARKS:** For attendance call 716-860-6044. +28 ft railroad 215 ft S of rwy cntrln parallel to Rwy 09-27.**AIRPORT MANAGER:** 716-860-6044**COMMUNICATIONS:** CTAF/AUNICOM 123.05**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BUF.**(H) DME** 116.4 BUF Chan 111 N42°55.74'

W78°38.78' 105° 1.6 NM to fld. 730/OE.

DME unusable:

036°-261° blo 11,000'

262°-275° blo 2,300'

276°-035° blo 6,000'

**COMM/NAV/WEATHER REMARKS:** Automated UNICOM. ADZY also avbl by calling 617-262-3825.