

LIBBY (S59) 7 S UTC-7(-6DT) N48°17.03' W115°29.41'
2605 B NOTAM FILE GTF

RWY 15-33: H5003X75 (ASPH-PFC) S-24 MIRL 0.4% up SE

RWY 15: REIL. PAPI(P2L)—GA 3.0° TCH 28'. Trees.

RWY 33: REIL. PAPI(P2L)—GA 3.75° TCH 31'. Trees.

SERVICE: FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 15-33, PAPI Rwy 15 and Rwy 33, and REIL Rwy 15 and Rwy 33—CTAF.

AIRPORT REMARKS: Attended continuously.

AIRPORT MANAGER: (406) 334-0969

WEATHER DATA SOURCES: AWOS-A 118.575 (406) 293-4631.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ SEATTLE CENTER APP/DEP CON 123.95

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE MLP.

MULLAN PASS (H) (H) VOR/DME 117.8 MLP Chan 125

N47°27.41' W115°38.76' 352° 50.0 NM to fld. 6100/15E.


VOR portion unusable:

060°-090° byd 20 NM blo 9,500'

GREAT FALLS

H-1D, L-13B

IAP



LIBERTY CO (See CHESTER on page 87)

LINCOLN (S69) 2 E UTC-7(-6DT) N46°57.28' W112°39.01'
4603 B NOTAM FILE GTF

RWY 04-22: H4240X75 (ASPH-PFC) S-12.5 MIRL 0.6% up NE

RWY 04: PAPI(P2L)—GA 4.0° TCH 32'. Trees.

RWY 22: Trees.

SERVICE: LGT ACTVT PAPI Rwy 04; MIRL Rwy 04-22—CTAF.

AIRPORT REMARKS: Unattended. Possible heavy helicopter use during summer. Intmt sn removal. 9' wildlife perimeter fence. Furnish own ropes.

AIRPORT MANAGER: 406-444-2506

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Helena Apch at 406-449-5756/5761, when Apch clsd ctc Salt Lake ARTCC at 801-320-2568.


RADIO AIDS TO NAVIGATION: NOTAM FILE GTF.

GREAT FALLS (H) (H) VORTACW 115.1 GTF Chan 98 N47°27.00'

W111°24.73' 224° 58.7 NM to fld. 3672/16E.

GREAT FALLS

L-13C



LINDEY'S LANDING WEST SPB (See SEELEY LAKE on page 121)