

BEND MUNI (BDN)(KBDN) 5 NE UTC-8(-7DT) N44°05.67' W121°12.01'

KLAMATH FALLS
H-1B, L-13A
IAP

3459 B TPA—See Remarks NOTAM FILE MMV
RWY 16-34: H5201X75 (ASPH) S-30 MIRL 1.1% up S
RWY 16: REIL. PAPI(P4L)—GA 3.0° TCH 38'. Trees. Rgt tfc.
RWY 34: REIL. PAPI(P4L)—GA 3.0° TCH 44'. Tree.
SERVICE: S4 **FUEL** 100LL, JET A **OX** 1, 3, 4 **LGT** ACTIVATE REIL
 Rwy 16 and Rwy 34; PAPI Rwy 16 and Rwy 34; MIRL Rwy
 16-34—CTAF.

NOISE: NS ABTMT procedures in effect, call FBO at 541-388-0019.

AIRPORT REMARKS: Attended Mon-Fri 1530-0200Z†, Sat-Sun
 1600-0100Z†. Be aware, intense helicopter training continually
 in progress. Glider opr on and invof arpt. Extv geese act reported
 on and near arpt year around, deer and other wildlife may be
 present. Calm wind rwy is Rwy 16. To avoid property damage
 exercise judgement and courtesy during run-up invof hangars.
 Apron areas may be heavily congested at times with svc vehicles,
 pedestrian and automobile tfc. Taxilanes and apron are NSTD, acft
 may rqr wing walkers, parking guidance and/or tugging at pilot
 discretion to insure acft clnc from obstacles. Both twys parallel to
 Rwy 16-34 marked by reflectors. TPA-rgt pat fixed wing to remain
 west of rwy using rgt pat Rwy 16 and left pat Rwy 34. Rotor wing
 to remain east of rwy and use rgt pat 34 and left pat 16. Fixed
 wing acft—no turns before end of rwy. Segmented circle located at
 northeast end of arpt.

AIRPORT MANAGER: 541-647-0828

WEATHER DATA SOURCES: AWOS-3 134.425 (541) 382-1477.

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.


AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE RDM.

DESCHUTES (H) (H) VORTACW 117.6 DSD Chan 123 N44°15.17' W121°18.21' 137° 10.5 NM to fld. 4103/18E.

VORTAC unusable:

220°-240° byd 30 NM



BOARDMAN (M5Ø) 4 SW UTC-8(-7DT) N45°48.89' W119°49.23'

SEATTLE
L-13A

396 B NOTAM FILE MMV
RWY 04-22: H4200X100 (ASPH) S-30 MIRL 0.7% up SW
RWY 22: Rgt tfc.

SERVICE: **LGT** ACTIVATE MIRL Rwy 04-22—122.9.

AIRPORT REMARKS: Unattended. Telephone avbl. Twy edge marked with blue
 reflectors. Rwy 04-22 cntrln in poor cond due to fading.

AIRPORT MANAGER: 541-481-7678

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE PDT.

PENDLETON (H) (H) VORTACW 114.7 PDT Chan 94 N45°41.91'
 W118°56.32' 267° 37.7 NM to fld. 1575/14E.

