

THERMOPOLIS

HOT SPRINGS CO (HSG)(KHSO) 10 NW UTC-7(-6DT) N43°42.82' W108°23.38'

CHEYENNE
H-3E, L-11E
IAF

4892 B NOTAM FILE CPR

RWY 05-23: H6370X75 (ASPH) S-30, D-45 PCN 29 F/A/X/T MIRL
0.3% up NE

RWY 05: REIL. PAPI(P2L)—GA 2.75° TCH 39'. Rgt tfc.

RWY 23: REIL. PAPI(P2L)—GA 2.75° TCH 39'.

SERVICE: FUEL 100LL, JET A LGT ACTVT REIL Rwy 05 and Rwy 23;
PAPI Rwy 05 and 23; MIRL Rwy 05-23—CTAF. PAPI Rwy 05 and 23
on consly dalgt hrs.

AIRPORT REMARKS: Attended 1400-2300Z† Mon-Fri. For svc after hrs
phone 307-921-8579. Fuel avbl with self-serve credit card. Full svc
avbl upon req. No call out fee for svc after hrs. Birds and wildlife on
and invof arpt.

AIRPORT MANAGER: (307) 867-2027

WEATHER DATA SOURCES: AWOS-3PT 121.125 (307) 867-2033.


COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ SALT LAKE CENTER APP/DEP CON 133.25

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at
801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE CPR.

BOYSEN RESERVOIR (H) (H) VORW/DME 117.8 BOY Chan 125
N43°27.79' W108°17.98' 329° 15.5 NM to fld.
7550/16E.



THOMAS MEML (See GLENDO on page 253)

TORRINGTON MUNI (TOR)(KTOR) 2 E UTC-7(-6DT) N42°03.87' W104°09.16'

CHEYENNE
H-5A, L-12F
IAF

4207 B NOTAM FILE TOR

RWY 10-28: H5703X75 (ASPH) S-33, D-45 PCN 9 F/B/X/T MIRL

RWY 10: PAPI(P2L)—GA 3.0° TCH 40'.

RWY 28: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Hill.

RWY 02-20: H3401X60 (ASPH)

RWY 02: Rgt tfc.

SERVICE: FUEL 100LL, JET A LGT ACTVT REIL Rwy 28; PAPI Rwy 10
and Rwy 28; MIRL Rwy 10-28—CTAF.

AIRPORT REMARKS: Attended 1500-0000Z†, exc natl hols. 100LL: For fuel
aft hrs call 307-338-8835. Deer and waterfowl on and invof arpt.
Emerg aft twr clsd ctc ARFF 307-772-6338.

AIRPORT MANAGER: 307-532-8551

WEATHER DATA SOURCES: ASOS 118.375 (307) 532-8958.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ DENVER CENTER APP/DEP CON 127.95

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE BFF.


SCOTTSBLUFF (H) (H) VORTAC 112.6 BFF Chan 73 N41°53.65'
W103°28.92' 276° 31.7 NM to fld. 4169/13E.

TACAN AZIMUTH & DME unusable:

025°-060° 25 NM blo 6,300'

310°-025° 25 NM blo 6,500'

NDB (MHW) 293 TOR N42°03.95' W104°09.20' at fld. 4200/11E. NOTAM FILE TOR.



UPTON MUNI (83V) 1 SW UTC-7(-6DT) N44°05.43' W104°38.45'

CHEYENNE

4290 B NOTAM FILE CPR

RWY 13-31: 3710X80 (GRVL-DIRT) MIRL

RWY 13: SAVASI(S2L)—GA 3.0° TCH 25'.

RWY 31: SAVASI(S2L)—GA 3.0° TCH 25'. Fence.

AIRPORT REMARKS: Unattended. For arpt attendant call 307-746-8411. Wildlife on and invof arpt. Radio ctdid airplane activity
within rwy environment. Ctc arpt mgr for rwy cond prior to winter ops phone 307-746-8411. No regular snow removal.
Hangars within transitional sfc. Rwy 13-31 marginal line of sight from rwy ends. +3' berms along rwy edges.

Non-working +3' lgts on non-frangible bases at rwy edges OTS indef. All arpt lgte OTS indef. Rwy 13 and Rwy 31 VASI
OTS indef.

AIRPORT MANAGER: (307) 746-8411

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.