

**MERRITT ISLAND** (COI)(KCOI) 0 S UTC-5(-4DT) N28°20.50' W80°41.13'

**JACKSONVILLE**

6 B LRA NOTAM FILE PIE

L-24F

**RWY 11-29:** H3601X75 (ASPH) S-22 PCN 23 F/A/X/T MIRL

IAP

**RWY 11:** PAPI(P2L)—GA 3.0° TCH 42'. Bldg.

**RWY 29:** PAPI(P2L)—GA 3.0° TCH 41'. Boat.

**SERVICE:** S4 FUEL 100LL, JET A LGT ACTVT MIRL Rwy 11-29 and rotating beacon—CTAF.

**NOISE:** Noise sensitive arpt. Voluntary noise abatement proc in efct. Climb out at best angle (VX), turn crosswind at 700 ft (mid-river, if poss) & merge with downwind t/c at 1000 ft pat alt. No touch-and-go ops btn 8 PM and 8 AM. No repetitive flt ops at the arpt btn 8 PM and 7 AM. No repetitive flt T ops on Sun and ntl hols. In lieu of touch-and-go ops perform full stop, taxi-back ops. Avoid flying at low alts ovr noise sensitive areas (Newfound Harbor Dr).

**AIRPORT REMARKS:** Attended 1300-0100Z. Banner towing invof arpt. 24 hr heli ops SW ramp. Patrick AFB (KCOF) Class D airspace in close proximity; KCOF crossing Rwy 11-29 has same orientation as Merritt Island Arpt.

**AIRPORT MANAGER:** 321-267-8780

**WEATHER DATA SOURCES:** AWOS-3 119.025 (321) 986-8864.

**COMMUNICATIONS:** CTAF/UNICOM 122.975

ORLANDO APP/DEP CON 134.95

**CLEARANCE DELIVERY PHONE:** For CD or to cnl IFR ctc Orlando Apch at 407-825-3398.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE ORL.


**ORLANDO (H) (H) VORTAC** 112.2 ORL Chan 59 N28°32.56' W81°20.10' 109° 36.4 NM to fld. 102/OE.

TACAN AZIMUTH unusable:

066°-084°

246°-289° byd 17 NM blo 2,000'

246°-289° byd 28 NM blo 2,500'



**MIAMI**

**DADE-COLLIER TRAINING AND TRANSITION** (TNT)(KTNT) 36 W UTC-5(-4DT) N25°51.71'

**MIAMI**

W80°53.82'

H-81, L-23C

13 B NOTAM FILE MIA

IAP

**RWY 09-27:** H10499X150 (ASPH-PFC) S-130, D-200, 2D-400, 2D/2D2-800 PCN 65 F/A/X/T HIRL

**RWY 27:** Trees. Rgt t/c.

**AIRPORT REMARKS:** Attended 1330-2230Z. Arpt CLOSED to public exc by arrangement with Miami-Dade Aviation Department, Miami 305-869-1660. No night-time ops exc with prior permission from Miami-Dade Avn Dept. 305-869-1660. Be alert to low flying National Park Service acft all quadrants. Men and eqpt working in buffer island btn Rwy 09-27 and twy. Wildlife oncly on and invof arpt. Fee for use for acft over 12,500 lbs. Twy H restricted to small fixed wing and rotary wing acft only.

**AIRPORT MANAGER:** (305) 869-1662

**WEATHER DATA SOURCES:** AWOS-3 119.075 (239) 695-9198.

**COMMUNICATIONS:** CTAF/UNICOM 123.0

**DADE COLLIER RCO** 122.3 (MIAMI RADIO)

**MIAMI APP/DEP CON** 128.6

**CLEARANCE DELIVERY PHONE:** For CD if una to ctc on FSS freq, ctc Miami Apch at 305-869-5432.

**AIRSPACE:** CLASS E svc 1200-2300Z Mon-Fri, 1200-1730Z Sat-Sun; other times CLASS G.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MIA.

**DOLPHIN (H) (H) VORTAC** 113.9 DHP Chan 86 N25°48.00' W80°20.94' 281° 29.9 NM to fld. 6/4W.

TACAN AZIMUTH unusable:

055°-065° byd 35 NM blo 3,000'

185°-195° byd 23 NM

226°-236° byd 35 NM

DME unusable:

055°-065° byd 35 NM blo 3,000'

