

SPRUCE PINE

AVERY CO(MORRISON FLD) (7A8) 4 NE UTC-5(-4DT) N35°56.72' W81°59.77'

ATLANTA
L-25C

2745 NOTAM FILE RDU

RWY 17-35: H3001X60 (ASPH) S-12.5 1.5% up N

RWY 17: Trees. Rgt tfc.

RWY 35: Trees.

SERVICE: S4 **FUEL** 100LL, JET A1 +

AIRPORT REMARKS: Attended Mon-Fri 1400-2200Z, Sat-Sun irreg. Unattended hol. Wildlife on and invof arpt. Ongoing construction activity with men and equipment on and invof Rwy 17-35. Fuel 24 hr credit card svc not operating call 828-387-7373 for fuel. FBO svc avbl contact 828-387-7373, 828-733-9073, or 828-260-3663. Arpt rstd to VFR only. Rwy 35 has 220' + trees and mountainous terrain 2,200' fm thld offset 400' right of cntrln. Rwy 35 mountainous terrain 6000' fm rwy end and 650' above rwy elevation on cntrln. Rwy 35 has 60' dropoff 250' from thr and 50 right of cntrln. Rwy 17 has 40' dropoff 300' from thr. Mil ops on and invof arpt. Gravel mining ops west of and adjacent to rwy with dirt bank ranging 26-48' high located 300-500' from rwy cntrln. High terrain all quadrants, daylight VFR ops only, Rwy 35 uphill grade, Rwy 17 rgt traffic preferred for takeoff. Rwy 17 preferred for tkfs, Rwy 35 preferred for ldgs.

AIRPORT MANAGER: (828) 387-7373

COMMUNICATIONS: CTAF/AUNICOM 123.0

Ⓡ **ATLANTA CENTER APP/DEP CON** 125.15

CLEARANCE DELIVERY PHONE: For CD ctc Atlanta ARTCC at 770-210-7692.

RADIO AIDS TO NAVIGATION: NOTAM FILE BNA.

HOLSTON MOUNTAIN (L) (L) VORTACW 114.6 HMV Chan 93 N36°26.22' W82°07.78' 172° 30.2 NM to fld. 4321/4W.

VOR unusable:

076°-126° byd 17 NM blo 8,500'

171°-178° byd 27 NM blo 10,000'

171°-178° within 27 NM blo 8,500'

260°-265° byd 36 NM blo 8,500'

HELIPAD H1: H40X40 (CONC) PERIMETER LGTS

HELIPAD H1: Trees.

STALS N35°14.63' W77°41.90' NOTAM FILE ISO.

CHARLOTTE

NDB (LOMW) 276 IS 049° 6.8 NM to Kinston Rgnl Jetport at Stallings Fld. 44/9W.

STANLY CO (See ALBEMARLE on page 283)

STAR

MONTGOMERY CO (43A) 0 NE UTC-5(-4DT) N35°23.08' W79°47.42'

CHARLOTTE

633 B NOTAM FILE RDU

L-25E, 36F

RWY 03-21: H4002X75 (ASPH) S-20 MIRL 1.5% up NE

IAP

RWY 03: PAPI(P2L)—GA 3.5° TCH 48'. Trees.

RWY 21: PAPI(P2L)—GA 4.0° TCH 33'. Thld dsplcd 458'. Pole.

SERVICE: LGT Actvt PAPI Rwy 03 & 21; MIRL Rwy 03-21—CTAF.

AIRPORT REMARKS: Unattended. Deer occasionally on rwy. 40 ft pline 350-750 ft fm thr Rwy 21 across & L of cntrln. 20-25 ft depression 180 ft S of Rwy 03 thr on cntrln. 35-40 ft drop-off 80 ft W of Rwy 03 cntrln; 30 ft drop-off 300 ft fm Rwy 21 thr on cntrln; 30 ft drop-off 80 ft R of Rwy 21 cntrln. Rwy 03 has uphill grade.

AIRPORT MANAGER: (910) 220-1218

COMMUNICATIONS: CTAF/AUNICOM 122.8

Ⓡ **FAYETTEVILLE APP/DEP CON** 127.8

CLEARANCE DELIVERY PHONE: For CD ctc Fayetteville Apch at 910-484-8012.

RADIO AIDS TO NAVIGATION: NOTAM FILE RDU.

SANDHILLS (L) (L) VORTACW 111.8 SDZ Chan 55 N35°12.93' W79°35.28' 319° 14.2 NM to fld. 588/3W.

VOR unusable:

075°-143°

144°-154° blo 6,000'

144°-154° byd 23 NM

155°-179° blo 5,000'

180°-264° blo 8,000'

301°-019° byd 10 NM blo 10,000'

DME unusable:

041°-092° blo 3,000'

TAC AZM unusable:

016°-050° byd 28 NM blo 3,000'