

DENVER

CENTENNIAL (APA)(KAPA) 15 SE UTC-7(-6DT) N39°34.21' W104°50.96'

DENVER
H-3F, 5A, L-10F, A
IAP, AD

5885 B AOE LRA NOTAM FILE APA
RWY 17L-35R: H10001X100 (ASPH-GRVD) S-56, D-75, 2S-95

PCN 26 F/C/X/T MIRL
RWY 17L: PAPI(P4L)—GA 3.0° TCH 47'. 1.0% up.
RWY 35R: MALSR. PAPI(P4L)—GA 3.0° TCH 49'. P-line. Rgt tfc. 0.8% down.
RWY 17R-35L: H7001X75 (ASPH-GRVD) S-30 PCN 23 F/C/X/T MIRL 0.9% up S
RWY 17R: REIL. PAPI(P4L)—GA 3.0° TCH 42'. Rgt tfc.
RWY 35L: REIL. PAPI(P4R)—GA 3.0° TCH 37'. Fence.
RWY 10-28: H4800X75 (ASPH-GRVD) S-12.5 PCN 17 F/A/Y/T MIRL 0.6% up W
RWY 10: PAPI(P2L)—GA 3.0° TCH 44'. Thld dsplcd 400'.
RWY 28: REIL. PAPI(P2L)—GA 3.0° TCH 41'. Pole.

SERVICE: S4 FUEL 100LL, JET A OX 1, 2

NOISE: Noise abatement proc in efct; noise office—303-790-0598. Rwy 35R crosswind/base leg N of Lincoln Ave; Rwy 17L crosswind/base leg S of Arapahoe Road; Rwy 17R-35L clsd tfc remain S of Arapahoe Road and E of Interstate 25; Rwy 10-28 avoid noise sensitive area 1 mi S and E of rwy.

AIRPORT REMARKS: Attended continuously. 100LL: Self serve fuel avbl.

Waterfowl on and in vicinity of arpt. Numerous cranes invov arpt. Nmrs flood lgts 1/2 SM N of thr; SS-0700Z±. Adzy density alt dspl lctd C-1, A-1, and A-18. +109' twr located 1800' east/northeast of Rwy 17L thld. All acft blo cert 70,000 lb max gross tkof wt and Stage III acft up to cert 75,000 lb max gross tkof wt may opr; one-time exception auwd by Exec Dir. Twy S2 clsd indef. Heli ops ctc FBO for Indg zone lctn; heli ops on front ramp not advised. User fee arpt: H24 U.S. Customs—303-768-0309. CTN: Ensure proper rwy alnmt; close spaced parl rwys. Arpt safety video—https://www.faa.gov/airports/runway_safety/videos/apa/. See Special Notices—USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

AIRPORT MANAGER: 303-790-0598

WEATHER DATA SOURCES: ASOS (720) 873-2799

COMMUNICATIONS: ATIS 120.3 303-799-6722 UNICOM 122.95

DENVER RCO 122.2 (DENVER RADIO)

DENVER APP/DEP CON 132.75

TOWER 118.9 GND CON 121.8 CLNC DEL 128.6

AIRSPACE: CLASS D svc continuous.

VOR TEST FACILITY (VOT) 108.2

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

FALCON (H) (H) VORTACW 116.3 FQF Chan 110 N39°41.41' W104°37.26' 225° 12.8 NM to fld. 5780/11E.

TACAN & DME unusable;

068°-088° byd 10 NM blo 11,500'

ILS/DME 111.3 I-APA Chan 50 Rwy 35R. Class IT. LOC unusable byd 13 NM blo 9,000'.

COMM/NAV/WEATHER REMARKS: Emerg frequency 121.5 not avbl at twr. Advise GND CON when ready for dep. GND CON will advise when to monitor the twr frequency.

HELIPAD H1: H50X50 (CONC) PERIMETER LGTS

HELIPORT REMARKS: Helipad H1: TLOF 50X50 ft; FATO 50X50 ft; ingress/egress 270. Helipad H1: H24 heli svc—303-799-0079.

