

PORT CLINTON

ERIE—OTTAWA INTL (PCW)(KPCW) 3 E UTC-5(-4DT) N41°30.98' W82°52.17'
590 B LRA NOTAM FILE CLE

DETROIT
H-10G, L-30F
IAP

RWY 09-27: H5646X100 (ASPH-GRVD) S-100 HIRL

RWY 09: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.

RWY 27: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Thld displcd 201'. Tree.

RWY 18-36: H4002X75 (ASPH) MIRL

SERVICE: S4 **FUEL** 100LL, JET A+ **OX** 1, 2, 3, 4 **LGT** Actvt REIL Rwy 09 & 27; HIRL Rwy 09-27; MIRL Rwy 18-36—CTAF. PAPI Rwy 09 & 27 opr consly.

AIRPORT REMARKS: Attended 1200-2300Z†. Birds and otr wildlife on and invof arpt. Taxilane A clsd to acft with wingspan more than 49'. Rwy 09-27 markings faded. Rwy 09-27 gross wgt: AUW-100. Cstms avbl 24 hrs 7 days per week, req must be made prior to arr, lcl office 419-732-4446. Hngr storage on avbly, aft hrs PPR. Rwy 09-27 calm wind rwy.

AIRPORT MANAGER: 419-734-6297

WEATHER DATA SOURCES: AWOS-3 118.775 (419) 734-9955.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **CLEVELAND APP/DEP CON** 126.35

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.

RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.

DRYER (VH) (DH) VOR/DME 113.6 DJB Chan 83 N41°21.48' W82°09.72' 292° 33.3 NM to fld. 780/5W.

VOR unusable:

001°-010° byd 40 NM

020°-024° byd 40 NM

034°-040° byd 40 NM

080°-095° byd 40 NM

110°-120° byd 40 NM

135°-145° byd 40 NM

160°-165° byd 40 NM

185°-195° byd 40 NM

210°-224° byd 40 NM

225°-235° byd 40 NM blo 11,000'

225°-235° byd 95 NM

225°-245° byd 20 NM blo 3,500'

245°-265° byd 40 NM

275°-285° byd 40 NM blo 18,000'

286°-355° byd 40 NM

PORT CLINTON NDB (MHW) 423 PCW N41°31.12' W82°52.13' at fld. 585/7W.

PORTAGE CO (See RAVENNA on page 304)

PORTSMOUTH

GREATER PORTSMOUTH RGNL (PMH)(KPMH) 10 NE UTC-5(-4DT) N38°50.43' W82°50.84'
663 B NOTAM FILE DAY

CINCINNATI
H-10G, L-26G
IAP

RWY 18-36: H5001X100 (ASPH) S-30, D-42, 2D-70 MIRL

RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 25'.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 31'. Brush.

SERVICE: S4 **FUEL** 100LL, JET A1+ **LGT** ACTIVATE REIL Rws 18 and 36, PAPI Rwy 18 and Rwy 36; MIRL Rwy 18-36—CTAF.

AIRPORT REMARKS: Attended Apr-Oct 1300-0100Z†, Nov-Mar 1300-2300Z†. Hill obstruction lgts 460' (1124') 1 mile south and 410' (1074') 1/2 mile northwest. No line of sight between rwy ends, acft not visible from one rwy end to other. Coml ldg fee waived with fuel purchase.

AIRPORT MANAGER: 740-820-2700

WEATHER DATA SOURCES: AWOS-3 125.175 (740) 820-2500.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **HUNTINGTON APP/DEP CON** 128.4

CLEARANCE DELIVERY PHONE: For CD ctc huntington ATCT at 304-453-2490.

RADIO AIDS TO NAVIGATION: NOTAM FILE LOU.

YORK (L) (L) VORTAC 112.8 YRK Chan 75 N38°38.65'

W82°58.70' 033° 13.3 NM to fld. 1040/5W.

