

APP CRS
267°

Rwy ldg
TDZE
893

Apt Elev
894

RNAV (GPS) RWY 26

LAKEFIELD (CQA)


▼

NA

DME/DME RNP-0.3 NA. Visibility reduction by helicopters NA. Baro-VNAV NA. Use Wapakoneta altimeter setting; when not received, use James M Cox Dayton Intl altimeter setting: increase LNAV/VNAV DA to 1349 feet and visibility all Cats ¼ SM; increase all MDA 80 feet and visibility LNAV and Circling Cat C ¼ SM.

MISSED APPROACH: Climb to 3000 direct EVOCO and on track 227° to COLMI and hold.

AXV AWOS-3PT 128.325	COLUMBUS APP CON 118.425 352.05	UNICOM 122.8 (CTAF)	123.3 0
-------------------------	------------------------------------	------------------------	---------



ELEV 894

TDZE 893

3000

EVOCO

tr 227°

COLMI

267° to RW26

4400 X 75

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 29).

4 NM Holding Pattern

3000

2600

2600

087°

267°

3000

GP 3.20° TCH 40

4.9 NM

6 NM

CATEGORY	A	B	C	D
LNAV/VNAV DA	1277-1¼	384 (400-1¼)		NA
LNAV MDA	1260-1	367 (400-1)		NA
CIRCLING	1360-1 466 (500-1)	1400-1 506 (600-1)	1480-1½ 586 (600-1½)	NA