


**FORT MORGAN MUNI** (FMM)(KFMM) 5 N UTC-7(-6DT) N40°20.13' W103°48.25'CHEYENNE  
H-5A, L-10F  
IAP

4595 B TPA-5626(1031) NOTAM FILE DEN

**RWY 14-32:** H5731X75 (ASPH) S-30 MIRL 1.5% up NW**RWY 14:** REIL. PAPI(P2L)—GA 3.0° TCH 28'.**RWY 32:** REIL. PAPI(P2L)—GA 3.0° TCH 27'. Road.**RWY 17-35:** 5216X80 (TURF-DIRT) 0.6% up N**RWY 35:** Road.**RWY 08-26:** 2468X100 (TURF)**RWY 26:** Road.**SERVICE:** FUEL 100LL, JET A1 **LGT** ACTIVATE REIL Rwy 14 and Rwy 32; MIRL Rwy 14-32—CTAF.**AIRPORT REMARKS:** Attended Mon-Sat 1500-0000Z±. Fuel avbl 24 hrs with credit card. Parachute Jumping. Be alert, intensive USAF student training invof Colorado Springs and Pueblo Colorado. Rwy 17-35, 21 road 100' east of and parallel to rwy cntrln full length. NOTE: See Special Notices—Aerobatic Operations in Colorado. USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.**AIRPORT MANAGER:** 970-867-8414**WEATHER DATA SOURCES:** AWOS-3PT 132.95 (970) 867-4823.**COMMUNICATIONS:** CTAF/UNICOM 123.05Ⓡ **DENVER CENTER APP/DEP CON** 118.475**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.**RADIO AIDS TO NAVIGATION:** NOTAM FILE AKO.**AKRON (H) (H) VORW/DME** 114.4 AKO Chan 91 N40°09.33' W103°10.78' 278° 30.6 NM to fld. 4623/13E.**FREMONT CO** (See CANON CITY on page 280)**GILL** N40°30.23' W104°33.18' NOTAM FILE DEN.CHEYENNE  
H-5A, L-10F**(VH) (DH) VORW/DME** 114.2 GLL Chan 89 210° 5.4 NM to Greeley-Weld Co. 4904/13E.

VOR unusable:

193°-204° byd 40 NM blo 7,800'

193°-204° byd 50 NM

226°-240° byd 40 NM

254°-263° byd 40 NM blo 16,000'

**RCO** 122.65 (DENVER RADIO)**GLENWOOD SPRINGS MUNI** (GWS)(KGWS) 3 S UTC-7(-6DT) N39°30.36' W107°18.55'DENVER  
L-9E

5916 NOTAM FILE DEN

**RWY 14-32:** H3305X50 (ASPH) S-15 0.3% up NW**RWY 14:** Trees.**RWY 32:** PAPI(P2L)—GA 4.0° TCH 30'. Road.**SERVICE:** S4 FUEL 100LL, JET A 0X3, 4**NOISE:** Noise abatement: When wind and weather permit use Rwy 32 for arrival and Rwy 14 for departure. No touch and go ldgs.**AIRPORT REMARKS:** Attended Mon-Fri 1500-0000Z±. Fuel avbl 24 hrs via self-serve credit card pump. Arpt Manager on call at 970-445-0965. FBO PH:970-945-3073. Gusty winds frequently in vicinity of arpt. Wildlife on and invof arpt. Numerous +25' buildings; trees; equipment; tie downs approximately 150' from centerline—both sides of rwy full length. Rwy 32 has 20' hangars and +30' antenna 200' left of centerline at thld. Paragliding ops vicinity 1 to 2 miles northwest of arpt up to 18,000' MSL. Automated super unicom. Click 3 times for arpt information.**AIRPORT MANAGER:** 970-445-0965**COMMUNICATIONS:** CTAF/AUNICOM 123.0**RCO** 122.2 (DENVER RADIO)**CLEARANCE DELIVERY PHONE:** For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DEN.**RED TABLE (VH) (DH) VORW/DME** 113.0 DBL Chan 77 N39°26.36' W106°53.68' 270° 19.7 NM to fld. 11800/12E.

VOR unusable:

040°-056° byd 40 NM

057°-074° byd 40 NM blo 16,300'

057°-074° byd 65 NM

075°-100° byd 40 NM

115°-130° byd 40 NM

160°-200° byd 40 NM

**COMM/NAV/WEATHER REMARKS:** Automated UNICOM, 3 clicks adzy.