

TACAN Y RWY 26

TACAN GSB
Chan 112

APCH CRS
261°

Rwy Idg 11,760
TDZE 109
Arprt Elev 109

AL-169 [USAF]

SEYMOUR JOHNSON AFB (KGSB)

▼ * When ALS inop, increase CAT AB RVR to 55, vis to 1 mile, CAT CDE vis to 1¼ miles.
** Circling N of Rwy 8-26 not authorized.

ALSF-1
A1

MISSED APPROACH: Climb to 2200 via GSB R-261 to TULME and hold.

ATIS ★
317.625

APP CON
258°-110° 123.7 290.9
111°-257° 119.7 273.6

TOWER ★
126.25 370.875

GND CON
138.1 275.8

CLNC DEL
128.025 270.8

453

601

R-261

081°

261°

GSB 20

SEYMOUR JOHNSON
Chan 112 GSB...

TULME
GSB 12

281

408

ZIDIS
GSB 3.9

BULBS
GSB 6

(IF) ZILOB
GSB 12

1600

(6)

2500

(6)

SNOW
485

GSB 18

2500

261°

081°

261°

R-081

(IAF) EEGEL
GSB 30
4000

LR-088

622

GSB 18

4000

539

(IAF) TBOLT
GSB 18
9000

325°

145°

GSB 28

MSA GSB 2.5 NM
3100
285°
2200

EMERG SAFE ALT 100 NM 3700

ELEV 109

TDZE 109

TWR
11,760 x 300
0.3% DOWN

A1

261°

2200
GSB R-261

TULME
R-261
12

TACAN

COMOZ
2.1

ZIDIS
3.9

BULBS
6

ZILOB
12

1600

880

3.04°
TCH 55

0.6

1.7 NM

2.2 NM

CATEGORY	A	B	C	D	E
S-26 *	540/24	431 (500-½)	540/40	431 (500-¾)	
CIRCLING **	580-1 471 (500-1)	600-1 491 (500-1)	680-1½ 571 (600-1½)	740-2 631 (700-2)	740-2¼ 631 (700-2¼)

HIRL Rwy 8-26

GOLDSBORO, NORTH CAROLINA

35° 20'N-77° 58'W

SEYMOUR JOHNSON AFB (KGSB)

Amtd 8 03NOV22

TACAN Y RWY 26

SE-2, 26 JAN 2023 to 23 FEB 2023

SE-2, 26 JAN 2023 to 23 FEB 2023