


LOC I-SAV 111.35	APP CRS 097°	Rwy Idg TDZE Apt Elev	9351 30 50
Chan 50 (Y)			

ILS or LOC RWY 10


SAVANNAH/HILTON HEAD INTL (SAV)

DME required.	MALSR	MISSED APPROACH: Climb to 800 then climbing left turn to 4000 on heading 330° and SAV VORTAC R-001 to TILLS INT/SAV 20 DME and hold.
For inop ALS, increase S-LOC 10 Cat C/D visibility to 1 3⁄8 SM.		

ATIS 123.75	SAVANNAH APP CON★ 125.3 371.875	SAVANNAH TOWER★ 125.975 (CTAF) 0 257.8	GND CON 121.9 348.6	CLNC DEL 119.55 291.775	UNICOM 122.95
-----------------------	---	--	-------------------------------	-----------------------------------	-------------------------



ELEV 50	D	TDZE 30
---------	---	---------



One Minute Holding Pattern	TILEE I-SAV 13.7 RADAR		SOVIE I-SAV 7.7 RADAR		800 ↑	4000 hdg 330°	SAV R-001	TILLS △
VGSi and ILS glidepath not coincident (VGSi Angle 3.00/TCH 69).								
6000 2600	← 277° 097° →	097°	2000	*I-SAV 3	I-SAV 1.7	* LOC only		
GS 3.00° TCH 50	2000		6 NM			4.7 NM		1.3 NM
CATEGORY	A		B		C		D	
S-ILS 10	230/18 200 (200-½)							
S-LOC 10	500/24 470 (500-½)		500/50 470 (500-1)					
CIRCLING	520-1 470 (500-1)		740-2 690 (700-2)		740-2¼ 690 (700-2¼)			