

ARRIVAL ROUTE DESCRIPTION

From LAWGR on track 248° to cross PPINT between 15000 and FL210 and at 250K.

LANDING RUNWAYS 7, 8: From PPINT on track 230° to cross BURRP between 15000 and 17000, then on track 247° to cross JEPHF between 13000 and 15000 and at 250K, then on track 236° to HAZLT, then on track 263° to cross HAITR at 11000 and at 210K, then on track 263°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 16L/R, 17L/R: From PPINT on track 274° to cross TAPME at or above 12000 and at 230K, then on track 274° to cross GRRUB at 11000 and at 210K, then on track 265°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 25, 26: From PPINT on track 235° to cross JIBBA at 13000, then on track 172° to cross RODEY at 13000 and at 210K, then on track 172°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 34L/R: From PPINT on track 230° to cross BURRP between 15000 and 17000, then on track 247° to cross JEPHF between 13000 and 15000 and at 250K, then on track 236° to HAZLT, then on track 236° to GRILA, then on track 173° to cross HIMOM at 11000 and at 210K, then on track 173°. Expect RADAR vectors to final approach course.

LANDING RUNWAYS 35L/R: From PPINT on track 230° to cross BURRP between 15000 and 17000, then on track 230° to cross YUPEE between 13000 and 15000 and at 250K, then on track 230° to FFFAT, then on track 173° to cross DOGGG at 11000 and at 210K, then on track 173°. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS: In the event of lost communications prior to runway transition assignment, when DEN is landing south, execute the ILS RWY 17R, when DEN is landing north, execute the ILS RWY 35R.