
MIDDLE BASS—EAST POINT (3W9) 1 NE UTC-5(-4DT) N41°41.67' W82°47.79'

DETROIT

582 NOTAM FILE CLE

RWY 09-27: 2085X67 (TURF)

RWY 09: Berm.

RWY 27: Road. Rgt tfc.

AIRPORT REMARKS: Attended May–Oct ireg, unatnrd Nov–Apr. Ocnl deer, birds and otr wildlife on and invof arpt. Rwy 09–27 soft and wet in spring. Nmrs trees and bldgs in close proximity to rwy. Exp sgfnt ws and turb on apch and dep when wind exceeds 10 Kt. For wind indir use segmented crc at 3T7 arpt.

AIRPORT MANAGER: 216-870-6513**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323.

MIDDLE BASS—EAST POINT (See MIDDLE BASS ISLAND on page 301)

MIDDLEFIELD
GEUGA CO (7G8) 1 SE UTC-5(-4DT) N41°26.98' W81°03.78'

DETROIT

1174 B TPA—2199(1025) NOTAM FILE CLE

L-30G

RWY 11-29: H3500X65 (ASPH) S-18.5 MIRL 0.5% up W

IAP

RWY 11: REIL. Thld dsplcd 179'. Tree.

RWY 29: REIL. PAPI(P2L)—GA 3.0° TCH 23'. Ground.

SERVICE: FUEL 100LL, MOGAS LGT ACTIVATE REIL Rwy 11 and Rwy 29; PAPI Rwy 29; MIRL Rwy 11–29—CTAF.

AIRPORT REMARKS: Attended Mon–Fri 1400–2200Z± ireg. Deer, birds & otr wildlife on and invof arpt. Extsv glider act on and invof arpt. Parl twy east of tee hngs clsd prmly.

AIRPORT MANAGER: 440-632-1884**COMMUNICATIONS:** CTAF/UNICOM 123.0

® CLEVELAND APP/DEP CON 125.35

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLE.**CHARDON (H) (H) VOR/DME** 112.7 CXR Chan 74 N41°31.02' W81°09.79' 137° 6.1 NM to fld. 1317/5W.

VOR portion unusable:

074°–084° byd 10 NM blo 3,300'

085°–099° byd 10 NM blo 11,000'

104°–180° byd 10 NM blo 6,000'

357°–073° byd 10 NM blo 11,000'

MIDDLETOWN RGNL/HOOK FLD (MWO)(KMWO) 2 N UTC-5(-4DT) N39°31.91' W84°23.79'

CINCINNATI

651 B NOTAM FILE DAY

H-10G, L-27E

RWY 05-23: H6100X100 (ASPH) S-66, D-78, 2S-99, 2D-140 MIRL

IAP

RWY 05: REIL. PAPI(P4R)—GA 3.0° TCH 22'. Trees.

RWY 23: REIL. PAPI(P4R)—GA 3.0° TCH 26'. Thld dsplcd 299'. Tree. Rgt tfc.

RWY 08-26: 3026X160 (TURF)

RWY 08: Thld dsplcd 951'. Trees.

RWY 26: Rgt tfc.

SERVICE: S4 FUEL 100LL, JET A OX4 LGT ACTIVATE REIL Rwy 05 and Rwy 23; MIRL Rwy 05–23—CTAF. PAPI Rwy 05 and Rwy 23 opr consly.

AIRPORT REMARKS: Attended 1300–2200Z±. Deer, birds, & otr wildlife on & invof arpt. Extensive Parachute Jumping.

Ultralights enter/exit pat at Rwy 08 to north — lwr than regular tfc pat. Ultralights do not fly south of Rwy 26. Rwy 08–26 end mkg white cones.

AIRPORT MANAGER: 513-705-1608**WEATHER DATA SOURCES:** AWOS-3 120.025 (513) 422-3505.**COMMUNICATIONS:** CTAF/UNICOM 123.0

® COLUMBUS APP/DEP CON 118.85

CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HUF.**RICHMOND (L) DME** 110.6 RID Chan 43 N39°45.30' W84°50.33' 123° 24.5 NM to fld. 1135.**HOOK FIELD NDB (MHW)** 239 HKF N39°29.93' W84°26.85' 054° 3.1 NM to fld. 786/4W. NOTAM FILE DAY.

NDB OTS indef

ONIDA NDB (LOMW) 239 MW N39°34.69' W84°19.41' 235° 4.4 NM to fld. 684/4W. NOTAM FILE DAY.**LOC** 111.1 I-MWO Rwy 23. LOM ONIDA NDB. COMLO unmonitored. COMLO unusable 060°–090° byd 10 NM.