

BURLINGTON INTL (BTV)(KBTv) P (ANG ARNG) 3 E UTC-5(-4DT) N44°28.32' W73°09.20'

335 B AOE Class I, ARFF Index B NOTAM FILE BTv

MONTREAL
H-11C, 12K, L-32G
IAP, AD

Rwy 15-33: H8319X150 (ASPH-CONC-GRVD) S-100, D-175, 2S-175, 2D-355 PCN 39 F/A/X/T HIRL

Rwy 15: MALSR. PAPI(P4R)—GA 3.0° TCH 51'. RVR-TR Trees. 0.6% up.

Rwy 33: MALSF. PAPI(P4R)—GA 3.2° TCH 53'. RVR-TR Thld dspld 500'. Trees.

Rwy 01-19: H4112X75 (ASPH) S-30, D-40, 2D-60 PCN 23 F/A/X/T MIRL

Rwy 01: PAPI(P4L)—GA 4.0° TCH 27'. Thld dspld 225'. Tree.

Rwy 19: PAPI(P4R)—GA 3.5° TCH 47'. Thld dspld 500'.

LAND AND HOLD—SHORT OPERATIONS

LDG RWY	HOLD—SHORT POINT	AVBL LDG DIST
Rwy 01	15-33	2600
Rwy 15	TXy A	3600
Rwy 33	01-19	2900

RUNWAY DECLARED DISTANCE INFORMATION

Rwy 01:	TORA-3611	TODA-3611	ASDA-3611	LDA-3386
Rwy 15:	TORA-7820	TODA-7820	ASDA-7820	LDA-7820
Rwy 19:	TORA-4111	TODA-4111	ASDA-4111	LDA-3386
Rwy 33:	TORA-8320	TODA-8320	ASDA-8320	LDA-7820

ARRESTING GEAR/SYSTEM

Rwy 15 TYPE H/BAK-12A (B) 1499 FT. TYPE H/BAK-12A (B) 1500 FT. **Rwy 33**

SERVICE: S4 FUEL 100LL, JET A OX 1, 3 LGT Dusk-Dawn. ACTVT MALSR Rwy 15; MALSF Rwy 33; PAPI Rwy 01 and 15; MIRL Rwy 01-19; HIRL Rwy 15-33; all twys—CTAF. PAPI Rwy 19 and 33 opr consly. NSTD twy lgts on Twy E.

MILITARY—A-GEAR Type H/BAK-12A(B) AER 33 lctd 1000 ft fm dthr. Rwy 15 & Rwy 33 A-G housings are non-frangible (26 in abv grd lev) lctd 250 ft fm rwy cntn. **JASU** 5(MD-4) 9(M32A-60) **FUEL** J8(Mil) 100LL, A **FLUID** SP LOX **OIL** O-133-148(Mil) SOAP.

AIRPORT REMARKS: Attended continuously. Birds & deer on & invof arpt. FBO clsd 0700-1400Z dly, exc 1 hr PPR 802-863-3626. Fighter acft rstd to tkf window of Mon-Sat 1330-0330Z, Sun 1700-0330Z. Caution: generating plant 2 NM from AER 15 produces steam which may obscure visibility on final apch. CAUTION: Phase II wildlife actvy durg migration, Mar-May and Aug 15-Nov 15. Acr ramp not avbl for pvt & chtr acft. Twy A btn Twy G and Twy C clsd to acft wingspan more than 118 ft exc 1 hr PPR 802-316-6014 dly. Twy L CLSD to acft over 60,000 lbs. Twy K CLSD to acft wingspan more than 49' and acft more than 12,500 lbs. Twys D, E, F and N clsd to civilian ops. Twys D, E, F, N, ANG and RNG ramps have unctl vehicle and acft. Twy M avbl for seasonal use, clsd drg winter months. ANG: Opr 1030-2100Z weekdays, exc hol, clsd Sat-Mon. PPR for fuel/prkg, etc ANG ops DSN 220-5213/5920/5267 C802-660-5213. All tsnt acft enr Ethan Allen trng site and R6501A must stop at AASF for rqr safety brief. ARFF avbl 24 hrs a day. A-Gear Type H/BAK-12A(B) AER 33 lctd 1000 ft fm dthr. Type H/BAK 12A(B) cable raised by twr on pilot req only. Fighter acft no low apchs. All other mil acft ltd to 2 practice apchs. Do not fly over hospital aprxly 1.5 NM west of Rwy 15 apch end. Rwy 01-19 south of Rwy 15-33 int to Twy C, single wheel 100, dual tandem wheel 355, south of Twy C int to south end of rwy, single wheel 30, dual wheel 60. Cold temperature airport. Altitude correction required at or below -10C. Ldg fee. Fee for itinerant acft greater than 6000 lbs. Beta Helipad pvt use only. Twy G btwn J and valley ramp clsd to acft wingspan gr than 156'.

AIRPORT MANAGER: 802-863-2874



CONTINUED ON NEXT PAGE

CONTINUED FROM PRECEDING PAGE

WEATHER DATA SOURCES: ASOS 123.8 (802) 657-4490.

COMMUNICATIONS: ATIS 123.8 (802-657-4424) CTAF 118.3 UNICOM 122.95

RCO 122.2 (BURLINGTON RADIO)

® APP/DEP CON 121.1 (1030-0500Z‡)

® BOSTON CENTER APP/DEP CON 120.35 (0500-1030Z‡)

TOWER 118.3 (1030-0500Z‡) GND CON 126.3 CLNC DEL 119.15 ANG OPS 134.1 41.2

CLEARANCE DELIVERY PHONE: For CD if twr clsd & una to ctc FSS freq, ctc Boston ARTCC at 603-879-6859.

AIRSPACE: CLASS C svc ctc APP CON svc 1030-0500Z‡; other times CLASS E.

VOR TEST FACILITY (VOT) 109.0

RADIO AIDS TO NAVIGATION: NOTAM FILE BTV.

(VL) (L) VORW/DME 117.5 BTV Chan 122 N44°23.83' W73°10.96' 031° 4.7 NM to fld. 417/15W.

VOR unusable:

030°-086° byd 40 NM

075°-132° byd 30 NM blo 9,000'

087°-097° byd 40 NM blo 9,000'

087°-097° byd 49 NM

098°-169° byd 40 NM

133°-165° byd 30 NM blo 8,000'

170°-180° byd 40 NM blo 5,800'

170°-180° byd 47 NM

181°-196° byd 40 NM

244°-292° byd 40 NM

340°-010° byd 40 NM

DME unusable:

075°-132° byd 30 NM blo 9,000'

133°-165° byd 30 NM blo 8,000'

(L) TACAN Chan 71 BJA (112.4) N44°28.62' W73°09.41' at fld. 308/15W.

TACAN AZIMUTH unusable:

010°-139°

140°-160° byd 29 NM

205°-208°

DME unusable:

010°-139°

140°-160° byd 29 NM

161°-227°

350°-009°

HERRO NDB (LOMW) 382 BT N44°31.94' W73°14.97' 146° 5.5 NM to fld. 130/15W.

ILS/DME 110.3 I-BTV Chan 40 Rwy 15. Class IB. LOM HERRO NDB. Unmonitored when ATCT clsd. LOC unusable byd 28° right of course.

ILS/DME 110.3 I-VOE Chan 40 Rwy 33. Class IA. LOC unusable byd 10 NM blo 2,700' LOC unusable byd 13 NM blo 4,700' Unmonitored when ATCT clsd.

CALEDONIA CO (See LYNDONVILLE on page 329)

DEERFIELD VALLEY RGNL (See WEST DOVER on page 334)

EDWARD F KNAPP STATE (See BARRE/MONTPELIER on page 324)

FRANKLIN CO STATE (See HIGHGATE on page 328)

HARTNESS STATE (SPRINGFIELD) (See SPRINGFIELD on page 333)

HERRO N44°31.94' W73°14.97' NOTAM FILE BTV.

MONTREAL

NDB (LOMW) 382 BT 146° 5.5 NM to Burlington Intl. 130/15W.
