

EASTERN SLOPES RGNL (See FRYEBURG on page 70)

EASTPORT MUNI (EPM)(KEPM) 1 W UTC-5(-4DT) N44°54.61' W67°00.76'

HALIFAX

45 B LRA NOTAM FILE EPM

L-321

RWY 15-33: H4002X75 (ASPH) S-30 MIRL 0.3% up SE

IAP

RWY 15: REIL. Tree.

RWY 33: REIL. PAPI(P2L)—GA 3.28° TCH 44'.

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 15, Rwy 33, PAPI Rwy 33, MIRL Rwy 15-33—CTAF.

AIRPORT REMARKS: Unattended. Deer and nmrs birds on and invof rwy. 24 hr self-svc fuel avbl with credit card. 40-50 ft obstn lgts on poles 250 ft R of cntrln near Rwy 15 end & apch area. Req cust at 207-853-4313.

AIRPORT MANAGER: 207-853-6060

WEATHER DATA SOURCES: AWOS-AV 122.8 (207) 853-0682. Frequency: 3 clicks to actvt.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ BOSTON CENTER APP/DEP CON 124.25

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE BGR.

PRINCETON (L) DME 114.3 PNN Chan 90 N45°19.75' W67°42.25' 130° 38.7 NM to fld. 398.

DME unusable:

300°-330° byd 25 NM blo 4,500'



ELIOT

SEACOAST AIRFIELD (3B4) 2 SE UTC-5(-4DT) N43°08.59' W70°46.41'

NEW YORK

125 NOTAM FILE BGR

L-32H, 33D

RWY 12-30: H2701X50 (ASPH) S-8 RWY LGTS(NSTD) 0.7% up NW

IAP

RWY 12: Trees.

RWY 30: Thld dspclcd 86'. Trees.

SERVICE: LGT SS-SR. Rwy 12-30 non-std LIRL spacing & color, no thr lgts.

AIRPORT REMARKS: Unattended. Birds & deer on & invof arpt. Rwy 12 and Rwy 30 markings non-std size, nrs and cntrln faded.

AIRPORT MANAGER: 949-378-8405

COMMUNICATIONS: CTAF 122.9

Ⓡ BOSTON APP/DEP CON 125.05

CLEARANCE DELIVERY PHONE: For CD ctc Boston Apch at 603-594-5551.

RADIO AIDS TO NAVIGATION: NOTAM FILE BGR.

ROLLINS NDB (MHW) 260 ESG N43°13.21'

W70°49.70' 168° 5.2 NM to fld. 72/16W.

