

NORMAN

UNIVERSITY OF OKLAHOMA WESTHEIMER (OUN)(KOUN) P (ARNG) 3 NW UTC-6(-5DT)

DALLAS-FT WORTH

H-6H, L-15D

IAP, AD

N35°14.73' W97°28.33'

1182 B TPA—See Remarks NOTAM FILE OUN

RWY 18-36: H5199X100 (ASPH-GRVD) S-30, D-50, 2D-100 MIRL

RWY 18: MALSR. PAPI(P4L)—GA 3.0° TCH 55'. Rgt ttc.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 40'.

RWY 03-21: H4748X100 (ASPH) S-30, D-50, 2D-100 MIRL

RWY 03: MALS. PAPI(P4L)—GA 3.0° TCH 40'.

RWY 21: PAPI(P4L)—GA 3.0° TCH 40'. Rgt ttc.

SERVICE: S4 FUEL 100LL, JET A LGT When twr clsd, ACTIVATE MIRL

Rwy 03-21 and Rwy 18-36; REIL Rwy 36; MALSR Rwy 18; MALS

Rwy 03—CTAF. **MILITARY—FUEL** A+ (avbl 1300-0400Z†,

C405-329-8062, OT 2 hr PN C405-623-2099, \$60 fee.)

(NC-100LL, A)

AIRPORT REMARKS: Attended 1200-0400Z†. Use extreme care coyotes on and invof rwy's. High density student ops invof arpt and 5 miles south. 180° turns prohibited on runways for all other than single engine light aircraft. TPA for hls 1682(500), Single engine 2182(1000); Multi-engine and jets 2682(1500).

AIRPORT MANAGER: 405-325-7233**WEATHER DATA SOURCES:** AWOS-3 119.55 (405) 325-7302.**COMMUNICATIONS:** CTAF 118.0 UNICOM 122.95

NORMAN RCO 122.4 (MC ALESTER RADIO)

④ OKE CITY APP/DEP CON 120.45


TOWER 118.0 (1400-0400Z†) GND CON 121.6

CLEARANCE DELIVERY PHONE: For CD ifun to ctc twr, ctc Oke City Apch at 405-681-5683.**AIRSPACE:** CLASS D svc 1400-0400Z†; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE OKC.

WILL ROGERS (H) (H) VORTACW 114.1 IRW Chan 88 N35°21.52' W97°36.55' 128° 9.5 NM to fld. 1230/7E.

LOC/DME 111.1 I-PHY Chan 48 Rwy 03. LOC/DME unmonitored when ATCT clsd.

ILS/DME 111.95 I-BWM Chan 56(Y) Rwy 18. Class IE. DME unusable byd 30° left of course.



NOWATA MUNI (H66) 2 NE UTC-6(-5DT) N36°43.26' W95°37.52'

KANSAS CITY

679 NOTAM FILE MLC

RWY 17-35: H2500X45 (ASPH) S-4

RWY 17: Trees.

RWY 35: Trees.

RWY 05-23: 2440X45 (TURF)

RWY 05: P-line.

RWY 23: Trees.

AIRPORT REMARKS: Unattended. Rwy 05-23 clsd indefly. Rwy 05-23 unidentifiable; rwy extremely rough and covered with tall grass and hay bales. -2' ditch at Rwy 23 thld, -12' ditch 220' from Rwy 35 thld. NOTE: See Special Notices—Aerobatic Practice Area.

AIRPORT MANAGER: (918) 273-3538**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.

OILLR N36°05.85' W95°53.33' NOTAM FILE TUL.

KANSAS CITY

NDB (LOMW) 338 TU 357° 6.0 NM to Tulsa Intl. 710/3E.

OKEENE

CHRISTMAN AIRFIELD (O65) 1 SE UTC-6(-5DT) N36°06.75' W98°18.52'

WICHITA

1208 B NOTAM FILE MLC

L-15D

RWY 17-35: H3000X60 (ASPH) S-12 MIRL

RWY 17: Tree.

SERVICE: LGT MIRL Rwy 17-35 preset low ints, to incr ints—CTAF.

AIRPORT REMARKS: Unattended.**AIRPORT MANAGER:** 580-822-3035**COMMUNICATIONS:** CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Vance Apch at 580-213-6765. when Vance Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.

RADIO AIDS TO NAVIGATION: NOTAM FILE MLC.

KINGFISHER (H) TACAN Chan 94 IFI (114.7) N35°48.32' W98°00.23' 312° 23.6 NM to fld. 1112/9E.