


FLOYDADA MUNI (41F) 1 N UTC-6(-5DT) N34°00.09' W101°19.82'
3187 B NOTAM FILE FTW
RWY 17-35: H4600X60 (ASPH) S-15 MIRL
RWY 17: PAPI(P2L)—GA 3.0° TCH 40'.
RWY 35: PAPI(P2L)—GA 3.0° TCH 39'. Bldg. Rgt tfc.
SERVICE: FUEL 100LL, JET A LGT Dusk-Dawn. MIRL Rwy 17-35 preset
to low intst; to incr intst or actvt—CTAF.
AIRPORT REMARKS: Attended Mon-Sat 1400-0000Z±. Extsv aerial ag ops.
AIRPORT MANAGER: 806-983-2314
COMMUNICATIONS: CTAF/UNICOM 122.8
® LUBBOCK APP/DEP CON 119.2 119.9
CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.
RADIO AIDS TO NAVIGATION: NOTAM FILE PVW.
PLAINVIEW (VL) (L) VORW/DME 112.9 PVW Chan 76 N34°05.17'
W101°47.41' 091° 23.5 NM to fld. 3400/11E.

DALLAS-FT WORTH
L-6H
IAP



FLUFY N31°13.13' W94°49.51' NOTAM FILE LFK.
NDB (LOMW) 350 LF 075° 4.0 NM to Angelina Co. 205/2E. NDB unmonitored.

HOUSTON

FLYIN ARMADILLO (See JACKSBORO on page 340)

FLYIN TIGER (See ANGLETON on page 243)

FLYING C (See SANGER on page 411)

FLYING H RANCH (See WHITESBORO on page 435)

FLYING V RANCH (See LOUISE on page 360)

FOLLETT/LIPSCOMB CO (T93) 1 E UTC-6(-5DT) N36°26.45' W100°07.43'
2601 NOTAM FILE FTW
RWY 17-35: H4073X60 (ASPH) S-18 1.7% up S
RWY 17: P-line.
RWY 35: Hill.
AIRPORT REMARKS: Unattended. No line of sight btn rwy ends. Rwy 17-35
13' wide strip of pavement alng west edge of rwy is spongy and will
not support listed wheel weight. Rwy 17-35 extensive pavement
cracking with vegetation growing through. loose stones on rwy. Rwy
17-35 no pavement markings.
AIRPORT MANAGER: 806-653-2601
COMMUNICATIONS: CTAF 122.9
® KANSAS CITY CENTER APP/DEP CON 126.95
CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at
913-254-8508.
RADIO AIDS TO NAVIGATION: NOTAM FILE GAG.
MITBEE (VH) (H) VORTACW 115.6 MMB Chan 103 N36°20.62'
W99°52.81' 286° 13.2 NM to fld. 2426/10E.

WICHITA
L-15C
IAP

