

MULESHOE MUNI (2T1) 4 SE UTC-6(-5DT) N34°11.11' W102°38.47'

ALBUQUERQUE

3779 B NOTAM FILE FTW

H-6G, L-6H

RWY 07-25: H5100X60 (ASPH) S-12.5 MIRL

IAP

RWY 07: PAPI(P2L)—GA 3.0° TCH 40'. Pole.

RWY 25: PAPI(P2L)—GA 3.0° TCH 40'.

SERVICE: FUEL 100LL LGT Actvt PAPI Rwy 07 and 25; MIRL Rwy 07-25-122.8.

AIRPORT REMARKS: Unattended. Deer on invof arpt. Fuel: 100LL: For emergency fuel call 806-272-4569, Central Dispatch.

AIRPORT MANAGER: 806-272-4528

COMMUNICATIONS: CTAF 122.9

® FORT WORTH CENTER APP/DEP CON 126.45

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

TEXICO (VH) (H) VORTACW 112.2 TXO Chan 59 N34°29.71' W102°50.38' 141° 21.0 NM to fld. 4060/11E.

VOR unusable:

095°-100° byd 40 NM

120°-130° byd 40 NM

210°-223° byd 40 NM blo 15,000'

224°-251° byd 40 NM

252°-262° byd 40 NM blo 18,000'

263°-272° byd 40 NM blo 18,000'


273°-283° byd 40 NM blo 6,000'

273°-283° byd 46 NM blo 7,000'

273°-283° byd 59 NM

284°-319° byd 40 NM

320°-035° byd 40 NM



MUNDAY MUNI (37F) 3 E UTC-6(-5DT) N33°28.12' W99°35.17'

DALLAS-FT WORTH

1474 B NOTAM FILE FTW

L-17B

RWY 17-35: H3200X50 (ASPH) S-4 LIRL

RWY 35: P-line.

SERVICE: LGT Beacon OTS. Actvt LIRL 17-35—CTAF. LIRL Rwy 17-35 OTS.

AIRPORT REMARKS: Attended Mon-Fri 1400-2200Z†.

AIRPORT MANAGER: 940-422-4331

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

GUTHRIE (L) DME 114.5 GTH Chan 92 N33°46.70' W100°20.17' 116° 41.9 NM to fld. 1941.

MUSTANG BEACH (See PORT ARANSAS on page 391)

MUSTANG ISLAND A85A MZG N27°43.62' W96°11.47'

AWOS-3 119.325 (504) 208-2390

L-20I, 21A, GOMW