



VORTAC RQZ 112.2 Chan 59	APP CRS 043°	Rwy Idg TDZE Apt Elev N/A N/A 764	VOR-B HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ)
--	------------------------	---	--

DME required.	MISSED APPROACH: Climbing left turn to 3000 direct RQZ VORTAC and hold.
	

AWOS-3PT 120.0	HUNTSVILLE APP CON★ 125.6 354.1	GCO 121.725	UNICOM 123.0 (CTAF) 0
--------------------------	---	-----------------------	--



HUNTSVILLE, ALABAMA	HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ)
Amdt 7B 28FEB19	34°52'N-86°33'W
	VOR-B